
World Housing Encyclopedia

an Encyclopedia of Housing Construction in
Seismically Active Areas of the World



an initiative of
Earthquake Engineering Research Institute (EERI) and
International Association for Earthquake Engineering (IAEE)

HOUSING REPORT

Buildings with hybrid masonry walls

| | |
|------------------|---|
| Report # | 8 |
| Report Date | 05-06-2002 |
| Country | CHILE |
| Housing Type | Confined Masonry Building |
| Housing Sub-Type | Confined Masonry Building with Concrete blocks, tie-columns and beams |
| Author(s) | Ofelia Moroni, Cristian Gomez, Maximiliano Astroza |
| Reviewer(s) | Sergio Alcocer |

Important

This encyclopedia contains information contributed by various earthquake engineering professionals around the world. All opinions, findings, conclusions & recommendations expressed herein are those of the various participants, and do not necessarily reflect the views of the Earthquake Engineering Research Institute, the International Association for Earthquake Engineering, the Engineering Information Foundation, John A. Martin & Associates, Inc. or the participants' organizations.

Summary

This housing type represents a common multi-family urban construction in Chile. Practice of this construction "mainly used for dwellings and for up to 4-story apartment buildings" began in the 1980s. The main load-bearing system consists of masonry walls in the transverse direction and reinforced concrete walls in the longitudinal direction. In some cases, longitudinal walls are of reinforced masonry construction (instead of concrete construction).

Masonry walls in the transverse direction are usually confined with concrete posts at the ends (such as is found in confined masonry construction). Buildings are usually regular in plan and in elevation. The seismic design code does not address this building type. However, the Chilean Ministry of Housing has issued specifications for 1- and 2-story dwellings, which have mainly been followed in the design (even in taller buildings of this type). Performance in the 1985 Lolleo earthquake was rather poor, with most buildings experiencing structural damage.

1. General Information

Buildings of this construction type can be found in all parts of Chile. This type of housing construction is commonly found in urban areas. This construction type has been in practice for less than 50 years.

Currently, this type of construction is being built.



Figure 1A: Typical building (photo)




Figure 1B: Typical housing complex

2. Architectural Aspects

2.1 Siting

These buildings are typically found in flat terrain. They do not share common walls with adjacent buildings. When separated from adjacent buildings, the typical distance from a neighboring building is 5-10 meters.

2.2 Building Configuration

The typical shape of a building plan is rectangular. These buildings are characterized with a regular structural layout, symmetrical with respect to at least one axis. As a result, there is a uniform distribution of stiffness both in plan and in elevation. In each longitudinal façade may be 3 to 4 openings of 0.8 to 1.5 m width probably equally spaced. The ratio for the overall window and door areas over the wall surface area is about 25 - 30%.

2.3 Functional Planning

The main function of this building typology is multi-family housing. Buildings of this type may be used for single-family houses, too. In a typical building of this type, there are no elevators and 1-2 fire-protected exit staircases. If single-story building, there is an additional door besides the main entry. If more than one floor, there is not an additional exit stair besides the main stairs.

2.4 Modification to Building

Typical patterns of modification observed are infill balconies or hillock on the top floor.




Figure 2A: Plan of a typical building




Figure 2B: Typical building plan

3. Structural Details

3.1 Structural System

| Material | Type of Load-Bearing Structure | # | Subtypes | Most appropriate type |
|------------------------|--------------------------------|---|--|-------------------------------------|
| Masonry | Stone Masonry Walls | 1 | Rubble stone (field stone) in mud/lime mortar or without mortar (usually with timber roof) | <input type="checkbox"/> |
| | | 2 | Dressed stone masonry (in lime/cement mortar) | <input type="checkbox"/> |
| | Adobe/ Earthen Walls | 3 | Mud walls | <input type="checkbox"/> |
| | | 4 | Mud walls with horizontal wood elements | <input type="checkbox"/> |
| | | 5 | Adobe block walls | <input type="checkbox"/> |
| | | 6 | Rammed earth/Pise construction | <input type="checkbox"/> |
| | Unreinforced masonry walls | 7 | Brick masonry in mud/lime mortar | <input type="checkbox"/> |
| | | 8 | Brick masonry in mud/lime mortar with vertical posts | <input type="checkbox"/> |
| | | 9 | Brick masonry in lime/cement mortar | <input type="checkbox"/> |
| | | 10 | Concrete block masonry in cement mortar | <input type="checkbox"/> |
| | Confined masonry | 11 | Clay brick/tile masonry, with wooden posts and beams | <input type="checkbox"/> |
| | | 12 | Clay brick masonry, with concrete posts/tie columns and beams | <input type="checkbox"/> |
| | | 13 | Concrete blocks, tie columns and beams | <input checked="" type="checkbox"/> |
| | Reinforced masonry | 14 | Stone masonry in cement mortar | <input type="checkbox"/> |
| | | 15 | Clay brick masonry in cement mortar | <input type="checkbox"/> |
| 16 | | Concrete block masonry in cement mortar | <input type="checkbox"/> | |
| Moment resisting frame | | 17 | Flat slab structure | <input type="checkbox"/> |
| | | 18 | Designed for gravity loads only, with URM infill walls | <input type="checkbox"/> |
| | | 19 | Designed for seismic effects, with URM infill walls | <input type="checkbox"/> |

| | | | | |
|---------------------|----------------------------|--|---|--------------------------|
| Structural concrete | Structural wall | 20 | Designed for seismic effects, with structural infill walls | <input type="checkbox"/> |
| | | 21 | Dual system – Frame with shear wall | <input type="checkbox"/> |
| | | 22 | Moment frame with in-situ shear walls | <input type="checkbox"/> |
| | | 23 | Moment frame with precast shear walls | <input type="checkbox"/> |
| | Precast concrete | 24 | Moment frame | <input type="checkbox"/> |
| | | 25 | Prestressed moment frame with shear walls | <input type="checkbox"/> |
| | | 26 | Large panel precast walls | <input type="checkbox"/> |
| | | 27 | Shear wall structure with walls cast-in-situ | <input type="checkbox"/> |
| 28 | | Shear wall structure with precast wall panel structure | <input type="checkbox"/> | |
| Steel | Moment-resisting frame | 29 | With brick masonry partitions | <input type="checkbox"/> |
| | | 30 | With cast in-situ concrete walls | <input type="checkbox"/> |
| | | 31 | With lightweight partitions | <input type="checkbox"/> |
| | Braced frame | 32 | Concentric connections in all panels | <input type="checkbox"/> |
| | | 33 | Eccentric connections in a few panels | <input type="checkbox"/> |
| | Structural wall | 34 | Bolted plate | <input type="checkbox"/> |
| 35 | | Welded plate | <input type="checkbox"/> | |
| Timber | Load-bearing timber frame | 36 | Thatch | <input type="checkbox"/> |
| | | 37 | Walls with bamboo/reed mesh and post (Wattle and Daub) | <input type="checkbox"/> |
| | | 38 | Masonry with horizontal beams/planks at intermediate levels | <input type="checkbox"/> |
| | | 39 | Post and beam frame (no special connections) | <input type="checkbox"/> |
| | | 40 | Wood frame (with special connections) | <input type="checkbox"/> |
| | | 41 | Stud-wall frame with plywood/gypsum board sheathing | <input type="checkbox"/> |
| | | 42 | Wooden panel walls | <input type="checkbox"/> |
| Other | Seismic protection systems | 43 | Building protected with base-isolation systems | <input type="checkbox"/> |
| | | 44 | Building protected with seismic dampers | <input type="checkbox"/> |
| | Hybrid systems | 45 | other (described below) | <input type="checkbox"/> |

Multiple Sub-Types exists such as 'Confined Masonry Building' or 'Reinforced Masonry Building'. The structural system is a RC wall in one direction and masonry.

3.2 Gravity Load-Resisting System

The vertical load-resisting system is reinforced concrete structural walls (with frame). Shear walls in both directions. Reinforced concrete slab. Average thickness 11 cm.

3.3 Lateral Load-Resisting System

The lateral load-resisting system is reinforced concrete structural walls (with frame). The main lateral load-resisting system in the buildings of this type consists of a hybrid system. In the transverse direction, the masonry walls it consists of partially reinforced or confined with reinforced concrete columns. In the longitudinal direction, there are reinforced masonry or reinforced concrete walls or partially confined walls (mainly used around the openings). These shear walls are tied together at floor levels by means of reinforced concrete beams. The reinforced masonry walls have a

10 mm diameter bar at each end plus 8 mm diameter bars distributed along the wall. Although the maximum allowed spacing between bars is 84 cm they are located between 120 and 150 cm. The diameter of the extreme bars is less than required (12 mm diameter) for dwellings higher than 2 story. Horizontal reinforcement does not meet the minimum steel ratio requirement of 0.06. The brick thickness in the exterior (façade) walls is 140 mm and 150 mm in the interior walls. Although the cores and voids containing reinforcement should be filled with grout, this is not accomplished in all cases. Most of the time the blocks are filled with the same mortar used in the horizontal joints. In addition, the size of the hollow cores in the ceramic unit is quite small so it is difficult to fill it. Concrete blocks (mostly used in the north of Chile) have larger hollow cores but they have water leakage problems and since 1997 the use of these blocks has been banned in Central Chile.

3.4 Building Dimensions

The typical plan dimensions of these buildings are: lengths between 6 and 12 meters, and widths between 10 and 20 meters. The building is 4 storey high. The typical span of the roofing/flooring system is 6 meters. Typical Plan Dimension: Unit average areas are 35-40 m². The typical storey height in such buildings is 2.3 meters. The typical structural wall density is none. 1.5 to 7.0 % in each direction. The average is about 3.2 % in each direction. The wall density per unit floor has been related to expected level of damage; for values lower than 1.15 % some moderate damage may be expected. Generally, lower values correspond to 3 or 4 story buildings. The wall density and wall density per unit floor variation with time are shown in Figure 5A, 5B and 5C.

3.5 Floor and Roof System

| Material | Description of floor/roof system | Most appropriate floor | Most appropriate roof |
|---------------------|---|-------------------------------------|-------------------------------------|
| Masonry | Vaulted | <input type="checkbox"/> | <input type="checkbox"/> |
| | Composite system of concrete joists and masonry panels | <input type="checkbox"/> | <input type="checkbox"/> |
| Structural concrete | Solid slabs (cast-in-place) | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| | Waffle slabs (cast-in-place) | <input type="checkbox"/> | <input type="checkbox"/> |
| | Flat slabs (cast-in-place) | <input type="checkbox"/> | <input type="checkbox"/> |
| | Precast joist system | <input type="checkbox"/> | <input type="checkbox"/> |
| | Hollow core slab (precast) | <input type="checkbox"/> | <input type="checkbox"/> |
| | Solid slabs (precast) | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| | Beams and planks (precast) with concrete topping (cast-in-situ) | <input type="checkbox"/> | <input type="checkbox"/> |
| | Slabs (post-tensioned) | <input type="checkbox"/> | <input type="checkbox"/> |
| Steel | Composite steel deck with concrete slab (cast-in-situ) | <input type="checkbox"/> | <input type="checkbox"/> |
| Timber | Rammed earth with ballast and concrete or plaster finishing | <input type="checkbox"/> | <input type="checkbox"/> |
| | Wood planks or beams with ballast and concrete or plaster finishing | <input type="checkbox"/> | <input type="checkbox"/> |
| | Thatched roof supported on wood purlins | <input type="checkbox"/> | <input type="checkbox"/> |
| | Wood shingle roof | <input type="checkbox"/> | <input type="checkbox"/> |
| | Wood planks or beams that support clay tiles | <input type="checkbox"/> | <input type="checkbox"/> |
| | Wood planks or beams supporting natural stones slates | <input type="checkbox"/> | <input type="checkbox"/> |
| | Wood planks or beams that support slate, metal, asbestos-cement or plastic corrugated sheets or tiles | <input type="checkbox"/> | <input type="checkbox"/> |
| | Wood plank, plywood or manufactured wood panels on joists supported by beams or walls | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| Other | Described below | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |

In the analysis the floor is considered to be a rigid diaphragm.

3.6 Foundation

| Type | Description | Most appropriate type |
|--------------------|--|-------------------------------------|
| Shallow foundation | Wall or column embedded in soil, without footing | <input type="checkbox"/> |
| | Rubble stone, fieldstone isolated footing | <input type="checkbox"/> |
| | Rubble stone, fieldstone strip footing | <input type="checkbox"/> |
| | Reinforced-concrete isolated footing | <input type="checkbox"/> |
| | Reinforced-concrete strip footing | <input checked="" type="checkbox"/> |
| | Mat foundation | <input type="checkbox"/> |
| | No foundation | <input type="checkbox"/> |
| Deep foundation | Reinforced-concrete bearing piles | <input type="checkbox"/> |
| | Reinforced-concrete skin friction piles | <input type="checkbox"/> |
| | Steel bearing piles | <input type="checkbox"/> |
| | Steel skin friction piles | <input type="checkbox"/> |
| | Wood piles | <input type="checkbox"/> |
| | Cast-in-place concrete piers | <input type="checkbox"/> |
| | Caissons | <input type="checkbox"/> |
| Other | Described below | <input type="checkbox"/> |

Usually the foundation does not have reinforcement, unless the soil is clay or silt. Concrete strip footing are used only under the walls plus reinforced tie beams in between.



Figure 3: Key load-bearing elements




Figure 4A: Critical structural details: elevation of a confined masonry wall




Figure 4B: Critical structural details: elevation of a confined masonry wall showing reinforcement details

CORTE C - C




Figure 4C: Critical structural details: vertical section through the wall showing reinforced concrete beams at floor levels




Figure 4D: Critical structural details: elevation of a confined masonry wall




Figure 5A: Wall density per floor area for different masonry buildings




Figure 5B: Wall density for hybrid masonry buildings




Figure 5C: Wall density per unit floor: hybrid masonry

4. Socio-Economic Aspects

4.1 Number of Housing Units and Inhabitants

Each building typically has 5-10 housing unit(s). 8 units in each building. Buildings may be from 1 to 4 floors. One-floor houses may be isolated or grouping up to 4 units. Two floor houses may be isolated or grouping up to 8 units. Up to 6 units per floor may exist in higher buildings. The number of inhabitants in a building during the day or business hours is less than 5. For larger buildings the daytime occupancy may be between 5-10. The number of inhabitants during the evening and night is 11-20. At present, the average size of a family is 5.5 persons, so if one unit is occupied by up to 3 families, the number of inhabitants in a building may be quite high.

4.2 Patterns of Occupancy

Typically one family occupies one housing unit. However, poor families may shelter 1 or 2 families, so-called "allegados".

4.3 Economic Level of Inhabitants

| Income class | Most appropriate type |
|--------------------------------------|-------------------------------------|
| a) very low-income class (very poor) | <input checked="" type="checkbox"/> |
| b) low-income class (poor) | <input checked="" type="checkbox"/> |
| c) middle-income class | <input checked="" type="checkbox"/> |
| d) high-income class (rich) | <input type="checkbox"/> |

Economic Level: For Very Poor Class, the Housing Unit Price is 8,000 and the Annual Income is 2000. For Poor Class, the Housing Unit Price is 25,000 and the Annual Income is 6,000. For Middle Class, the Housing Unit Price is 50,000 and the Annual Income is 12,000.

| Ratio of housing unit price to annual income | Most appropriate type |
|--|-------------------------------------|
| 5:1 or worse | <input type="checkbox"/> |
| 4:1 | <input checked="" type="checkbox"/> |
| 3:1 | <input type="checkbox"/> |
| 1:1 or better | <input type="checkbox"/> |

| What is a typical source of financing for buildings of this type? | Most appropriate type |
|---|-------------------------------------|
| Owner financed | <input checked="" type="checkbox"/> |
| Personal savings | <input checked="" type="checkbox"/> |
| Informal network: friends and relatives | <input checked="" type="checkbox"/> |

| | |
|---|-------------------------------------|
| Small lending institutions / micro-finance institutions | <input checked="" type="checkbox"/> |
| Commercial banks/mortgages | <input checked="" type="checkbox"/> |
| Employers | <input type="checkbox"/> |
| Investment pools | <input checked="" type="checkbox"/> |
| Government-owned housing | <input type="checkbox"/> |
| Combination (explain below) | <input type="checkbox"/> |
| other (explain below) | <input type="checkbox"/> |

This type of dwelling for poor and very poor people is subsidized by the State. In each housing unit, there are 1 bathroom(s) without toilet(s), no toilet(s) only and 1 bathroom(s) including toilet(s).

4.4 Ownership

The type of ownership or occupancy is renting, outright ownership and ownership with debt (mortgage or other).

| | |
|---|-------------------------------------|
| Type of ownership or occupancy? | Most appropriate type |
| Renting | <input checked="" type="checkbox"/> |
| outright ownership | <input checked="" type="checkbox"/> |
| Ownership with debt (mortgage or other) | <input checked="" type="checkbox"/> |
| Individual ownership | <input type="checkbox"/> |
| Ownership by a group or pool of persons | <input type="checkbox"/> |
| Long-term lease | <input type="checkbox"/> |
| other (explain below) | <input type="checkbox"/> |

5. Seismic Vulnerability

5.1 Structural and Architectural Features

| Structural/ Architectural Feature | Statement | Most appropriate type | | |
|---|--|-------------------------------------|-------------------------------------|-------------------------------------|
| | | True | False | N/A |
| Lateral load path | The structure contains a complete load path for seismic force effects from any horizontal direction that serves to transfer inertial forces from the building to the foundation. | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Building Configuration | The building is regular with regards to both the plan and the elevation. | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Roof construction | The roof diaphragm is considered to be rigid and it is expected that the roof structure will maintain its integrity, i.e. shape and form, during an earthquake of intensity expected in this area. | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| Floor construction | The floor diaphragm(s) are considered to be rigid and it is expected that the floor structure(s) will maintain its integrity during an earthquake of intensity expected in this area. | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Foundation performance | There is no evidence of excessive foundation movement (e.g. settlement) that would affect the integrity or performance of the structure in an earthquake. | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Wall and frame structures-redundancy | The number of lines of walls or frames in each principal direction is greater than or equal to 2. | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

| | | | | |
|-------------------------------|---|-------------------------------------|-------------------------------------|-------------------------------------|
| Wall proportions | Height-to-thickness ratio of the shear walls at each floor level is: Less than 25 (concrete walls); Less than 30 (reinforced masonry walls); Less than 13 (unreinforced masonry walls); | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Foundation-wall connection | Vertical load-bearing elements (columns, walls) are attached to the foundations; concrete columns and walls are doweled into the foundation. | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Wall-roof connections | Exterior walls are anchored for out-of-plane seismic effects at each diaphragm level with metal anchors or straps | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| Wall openings | The total width of door and window openings in a wall is: For brick masonry construction in cement mortar : less than 1/2 of the distance between the adjacent cross walls; For adobe masonry, stone masonry and brick masonry in mud mortar: less than 1/3 of the distance between the adjacent cross walls; For precast concrete wall structures: less than 3/4 of the length of a perimeter wall. | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Quality of building materials | Quality of building materials is considered to be adequate per the requirements of national codes and standards (an estimate). | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Quality of workmanship | Quality of workmanship (based on visual inspection of few typical buildings) is considered to be good (per local construction standards). | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Maintenance | Buildings of this type are generally well maintained and there are no visible signs of deterioration of building elements (concrete, steel, timber) | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Additional Comments | Usually the roof is made of wood planks or beams that support slate, metal, asbestos-cement or plastic corrugated sheets or tiles. | | | |

5.2 Seismic Features

| Structural Element | Seismic Deficiency | Earthquake Resilient Features | Earthquake Damage Patterns |
|------------------------|---|-------------------------------|--|
| Wall | Unknown shear strength, so it is difficult to get flexural ductile failure. It is difficult to achieve good anchoring and bonding conditions especially if poor quality masonry units and poor mortar instead of grout are used. Hollow sizes in clay units are inappropriate. Vertical reinforcements without grouting are ineffective. Lack of reinforced concrete tie-post may cause shear failure and out-of-plane bending effects. The tensile steel bar in one end does not represent a proper tie-post. Lack of appropriate reinforcement at opening edges. | High wall density. | Perimeter walls with shear cracks, out of plumb and separations at the corners. Crushed at the wall bottom due to compression failure-interior walls usually confined had only small cracks. |
| Frame (columns, beams) | | | |
| Roof and floors | | | |
| | | | |

5.3 Overall Seismic Vulnerability Rating

The overall rating of the seismic vulnerability of the housing type is B: MEDIUM-HIGH VULNERABILITY (i.e., poor seismic performance), the lower bound (i.e., the worst possible) is A: HIGH VULNERABILITY (i.e., very poor seismic performance), and the upper bound (i.e., the best possible) is C: MEDIUM VULNERABILITY (i.e., moderate seismic performance).

| | | | | | | |
|---------------------|-------------------------------------|--------------------------|-------------------------------------|--------------------------|--------------------------|--------------------------|
| Vulnerability | high | medium-high | medium | medium-low | low | very low |
| | very poor | poor | moderate | good | very good | excellent |
| Vulnerability Class | A | B | C | D | E | F |
| | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

5.4 History of Past Earthquakes

| Date | Epicenter, region | Magnitude | Max. Intensity |
|------|-------------------|-----------|----------------|
| 1971 | La Ligua | 7.5 | IX |
| 1985 | Llolleo | 7.8 | VIII |
| 1997 | Punitaqui | 6.8 | VI-VII |

Due to 1971 earthquake, about 1000 one-story houses at Choapa Valley partially collapsed. The masonry walls had tie-reinforced concrete beam and some tensile bars at the extremes of the walls or at the corners of joint between walls. After the 1985 earthquake the Ministry of Housing appointed an especial committee to review the seismic effects on social dwellings. About 84,000 units were reviewed, concluding that 50% of the units had some structural damage, being 2.6% of it hybrid reinforced masonry 3 or 4 story buildings and all of them had some type of damage. The following characteristic damage patterns were observed: (1) perimeter walls with shear cracks, out of plumb and separations at the corners, (2) crushed at the wall bottom due to compression failure, (3) interior walls usually confined had only small cracks. Some damage occurred in houses located in Illapel during 1997 earthquake due to differential settlement on a sloped terrain.



Figure 6A: Photograph illustrating typical earthquake damage (1997 Punitaqui earthquake)



Figure 6B: Earthquake damage (1997 Punitaqui earthquake)



Figure 6C: Earthquake damage (1997 Punitaqui earthquake)

6. Construction

6.1 Building Materials

| Structural element | Building material | Characteristic strength | Mix proportions/dimensions | Comments |
|--------------------------|-------------------------------|-------------------------|----------------------------|---------------|
| Walls | Clay brick, Artisan brick | 6-12 / 2-8 | 14 x 29 / 20 x 30 | 10-20 / 15-40 |
| Foundation | Concrete block | 3-10 | 39x19x9 / 39x14x9 | 5-12 |
| Frames (beams & columns) | Beams: Concrete Steel A44-28H | 18 - 20 | | |
| Roof and floor(s) | | | | |

6.2 Builder

Construction companies, which are hired by the state are constructing this type of buildings.

6.3 Construction Process, Problems and Phasing

One contractor builds large quantities of this type of buildings, so project management and control techniques are used in order to increase productivity and to diminish cost. However, inspection and supervision is difficult because too many activities are done simultaneously. When constructing the vertical reinforcing bars are usually first placed into position before laying the masonry units. Then, the horizontal bars can be placed in horizontal mortar joints. Finally, vertical reinforcement is grouted as the work progresses. For confined walls the brick are laid in first place and then the columns and beams are concrete against the walls. ICH is developing guidelines to build this type of structures properly. With respect to equipment the following is commonly used: concrete mix, trucks, traveling crane, wind. The construction of this type of housing takes place in a single phase. Typically, the building is originally designed for its final constructed size.

6.4 Design and Construction Expertise

The structural engineer will have 6 years of studies and more than 3-5 years of experience. The construction engineer may have 6 years of studies and less experience than the structural engineer. For private projects there is not compulsory inspection during the construction and no peer revision of the structural project, but when inspection does exist larger masonry compression strength are allowed. The designer may visit the construction site once or twice during the construction. Projects hired by the state are revised and inspected during construction by SERVIU. See 'Construction process'.

6.5 Building Codes and Standards

This construction type is not addressed by the codes/standards of the country. The seismic loads are determined based on the NCh433.0f96 "Seismic Design for Buildings". In general, these buildings are quite stiff and they must resist a base shear of 10-22% depending on the seismic zone; the story drift must be equal or less than 0.002. A specific code addressing this type of construction does not exist. Designers follow some requirements of NCh1928.0f93 (Reinforced Masonry Design Code) or NCh 2123.0f97 (Confined Masonry Design Code) which are too strict. In general, designers follow guidelines prepared by the Ministry of housing for 1 or 2 storied houses, independently of the number of floors of the project. The building design must follow the NCh433.0f96 code. SERVIU, a governmental office which is in charge of social dwellings has a professional staff to review the projects and to inspect during construction. In case of damage an arbitrage process may take place at the court of justice.

6.6 Building Permits and Development Control Rules

This type of construction is an engineered, and not authorized as per development control rules. Building permits are required to build this housing type.

6.7 Building Maintenance

Typically, the building of this housing type is maintained by Owner(s), Tenant(s), No one and others. As it was pointed out, after the 1985 earthquake a committee was appointed by the Ministry of Housing, in order to review the damaged buildings, to prepare restoration projects, and to supervise its execution.

6.8 Construction Economics

The total cost of this type of building can be blotted out in main structure 62%, finishing work 25%, urbanization, operating cost and profit 13%. The cost of one unit is 200 to 400 UF (area 45 m²), \$78,000 to \$140,000 /m² (US\$ 135 - US\$ 245 /m²). Better quality unit may cost up to \$174,000 /m² (US\$ 300/m²). At present, depending on the technology used, the construction may take 2 - 3 stories per month of several units simultaneously built.

7. Insurance

Earthquake insurance for this construction type is typically unavailable. For seismically strengthened existing buildings or new buildings incorporating seismically resilient features, an insurance premium discount or more complete coverage is unavailable. Earthquake insurance is available as a supplement of other insurances (fire, robbery, etc) and people living in these buildings do not have money to pay for that. Repair costs in order to bring the building into the same condition as it was before the earthquake.

8. Strengthening

8.1 Description of Seismic Strengthening Provisions

Strengthening of Existing Construction :

| Seismic Deficiency | Description of Seismic Strengthening provisions used |
|---------------------------------|---|
| Lack of appropriate confinement | The strengthening procedure consist in confining the masonry wall with reinforced concrete tie-column and tie-beam. This may cost up to 20% of the original cost. With this procedure ductility is also improved. |

8.2 Seismic Strengthening Adopted

Has seismic strengthening described in the above table been performed in design and construction practice, and if so, to what extent?

Only after the earthquake on March 3, 1985.

Was the work done as a mitigation effort on an undamaged building, or as repair following an earthquake?

As a repair following earthquake damage.

8.3 Construction and Performance of Seismic Strengthening

Was the construction inspected in the same manner as the new construction?

Yes.

Who performed the construction seismic retrofit measures: a contractor, or owner/user? Was an architect or engineer involved?

A contractor hired by the Ministry of Housing.

What was the performance of retrofitted buildings of this type in subsequent earthquakes?

No subsequent earthquakes has hit that zone yet.

Reference(s)

1. Apuntes de Curso: CI 52-H. Dise
M. Astroza
Estructuras y Construcci 2000
2. Chile, 50 a
L. Bravo and C. Martinez
Universidad de Valpara 1993
3. Influencia del suelo de fundaci
P. Escobar
Civil Engineer Thesis, Universidad de Chile 1986
4. Chile, 50 a
L. Bravo and C. Martinez
Universidad de Valpara 1993
5. Catastro de viviendas con da
6. Caracter
J. Giadalah
Civil Engineer Thesis, Universidad de Chile 2000
7. Caracterizaci
C. Gomez
Civil Engineer Thesis, Universidad de Chile. 2001
8. Construcci
ICH
Instituto del Cemento y Hormig 1992
9. Anuario de Edificaci
INE, (1980-1986), (1994-1998)
Instituto Nacional de Estad
10. Alba
INN NCh1928.o#3
11. C
INN NCh2123.O#7
12. Alternativas de estructuraci
V. Palma
Civil Engineer Thesis, Universidad de Chile 1998

Author(s)

1. Ofelia Moroni
Civil Engineer/Assistant Professor, University of Chile
Casilla 228/3, Santiago , CHILE
Email:mmoroni@cec.uchile.cl FAX: 562-6892833
2. Cristian Gomez
Civil Engineer/Research Assistant, University of Chile
Casilla 228/3, Santiago 228/3, CHILE
Email:rcgomez@cec.uchile.cl FAX: 562-6892833
3. Maximiliano Astroza
Civil Engineer/ Associate Professor, University of Chile
Casilla 228/3, Santiago , CHILE
Email:mastroza@cec.uchile.cl FAX: 562-6892833

Reviewer(s)

1. Sergio Alcocer
Director of Research
Circuito Escolar Ciudad Universitaria, Institute of Engineering, UNAM
Mexico DF 4510, MEXICO
Email:salcoce@iingen.unam.mx FAX: +52 (55) 56162894

Save page as

