
World Housing Encyclopedia

an Encyclopedia of Housing Construction in
Seismically Active Areas of the World



an initiative of
Earthquake Engineering Research Institute (EERI) and
International Association for Earthquake Engineering (IAEE)

HOUSING REPORT

Reinforced Concrete Moment Frame Building without Seismic Details

Report #	111
Report Date	14-09-2004
Country	USA
Housing Type	RC Moment Frame Building
Housing Sub-Type	RC Moment Frame Building : Designed for gravity loads only, with URM infills
Author(s)	Heidi Faison, Craig D. Comartin, Kenneth Elwood
Reviewer(s)	Mahmoud M. Hachem, Ayhan Irfanoglu

Important

This encyclopedia contains information contributed by various earthquake engineering professionals around the world. All opinions, findings, conclusions & recommendations expressed herein are those of the various participants, and do not necessarily reflect the views of the Earthquake Engineering Research Institute, the International Association for Earthquake Engineering, the Engineering Information Foundation, John A. Martin & Associates, Inc. or the participants' organizations.

Summary

This report examines reinforced concrete buildings that use moment-resisting frames without ductile detailing to resist seismic loads. While this building type is predominantly used for office buildings and hotels, it is also used in urban areas for multi-family dwellings

(condominiums) and university dormitories. It can be found in most urban areas across the country, though it is of particular concern in areas of high seismic hazard like California, Alaska, Washington, and Oregon. Building codes did not include requirements for special seismic detailing of reinforced concrete structures until the 1970's when several earthquakes demonstrated the need for more ductile design. These buildings are vulnerable to numerous failure modes including: failure of column lap splices; strong beam/weak column failures; captive column failure; punching shear failures in flat plate slabs; and shear and axial load failure of columns with wide transverse reinforcement spacing. A discontinuity in stiffness and strength at the bottom story, due to a soft story, often results in a concentration of earthquake damage at the building base. Several examples of past earthquake behavior are given in this report as well as discussion of various retrofit options.

1. General Information

Buildings of this construction type can be found in most urban areas across the country, including California. Percentage of housing stock is unknown, but is expected to vary based on region. This type of housing construction is commonly found in both sub-urban and urban areas. This construction type has been in practice for less than 75 years.

Currently, this type of construction is being built. This construction type is still being practiced in regions of low seismic hazard, but not in high seismic hazard regions like California where code provisions require ductile detailing.




Figure 1: Typical Building Plan (Holiday Inn, Van Nuys, CA) [1]




Figure 2: Typical Elevation (Holiday Inn, Van Nuys, CA) [1]




Figure 3: Typical Details (Holiday Inn, Van Nuys, CA) [1]




Figure 4: Typical Exterior Frame Detail [12]




Figure 5: Typical Column Detail Elevation




Figure 6: Overall view of the 1200 L Street Apartment building, Anchorage, Alaska after damage from the 1964 earthquake. This 14-story reinforced concrete structure has a basic lateral-resisting structural system and a series of slender walls coupled by s



Figure 7: Close-up of characteristic X-shaped cracks and failure of coupling girders or short spandrel girders in the L street apartment building, Anchorage, Alaska. These girders were not properly designed for the shear demands. [10]



Figure 8: Damage to West Anchorage High School from the 1964 Alaska earthquake. Window wall fell inwards into the classrooms. Note sag in roof due to failure of reinforced concrete diaphragm. [9]



Figure 9: Detail view of damage to the column and beam joints at West Anchorage High School, Anchorage, Alaska. [9]



Figure 10: Olive View Hospital, Psychiatric Unit, 1971 San Fernando Earthquake. This unit was a 2-story reinforced concrete building. The structural system was a moment resisting frame. However, in the second story there were masonry walls that added sign



Figure 11: Olive View Hospital, Medical Treatment and Care Unit, 1971 San Fernando earthquake. View of the end of one of the four wings of this 5-story reinforced concrete building after the earthquake. Note the large distortion of the first soft story co



Figure 12: Damage to Olive View Hospital bottom story moment frame columns from the San Fernando earthquake. [9]




Figure 13: Details of Olive View Hospital Columns. [8]



Figure 14: Example of damage to the corner columns at Olive View Hospital which was the result of poor seismic detailing. [9]



Figure 15: Detail view of the behavior of one of the first and second story columns in the Olive View Medical Treatment and Care Unit during the 1971 San Fernando Earthquake. Note the large permanent distortion of the first story column (because it was pa



Figure 16: Detailed view of column with spiral confinement steel. The spiral confinement steel helped keep the concrete core intact. The longitudinal reinforcement is tied on the exterior of the spiral; this detail leaves the longitudinal steel vulnerable



Figure 17: Olive View Hospital, 1971 San Fernando earthquake. Close-up of the top of the column illustrating how the concrete in this critical region has been disrupted (broken off) as a consequence of the premature ending of the spiral reinforcement. [10]




Figure 18: Collapse of the San Fernando Veterans Administration Hospital from the 1971 San Fernando earthquake. The image is from air photos taken shortly after the event. [9]




Figure 19: During the 1979 Imperial Valley earthquake, the 6-story reinforced concrete Imperial County Services Building developed significant inertia forces simultaneously in the two main directions (illustrated in red). As a result, the corner columns o



Figure 20: View of the 1979 Imperial Valley earthquake damage in the first story columns located in the east end of the Imperial County Services building. Note the explosive type of failure just above the ground and the offset between the columns and the



Figure 21: Close-up of the failure at the bottom of a column of the Imperial County Services building. The failure occurred in the zone of the column where there was not adequate confinement of the concrete and no shear reinforcing steel. [9]



Figure 22: View of Holiday Inn, Van Nuys, CA with damage from the 1994 Northridge earthquake. The lateral system consists of reinforced concrete perimeter moment frames. Column damage required the placement of temporary shoring where the vertical load ca



Figure 23: Damage to the Holiday Inn, Van Nuys primarily consisted of shear failure of the columns and subsequent buckling of column vertical reinforcing between the ties where added confinement provided by the concrete cover was no longer available due t



Figure 24: Damage from the 1994 Northridge earthquake to the perimeter moment frames of the Champaign Tower in Santa Monica, CA. [5]



Figure 25: Balcony parapets induced short-column effects in the Champaign Tower moment frames. Typical X-shaped shear cracking from the short-column behavior is shown. [5]



Figure 26: Damage to the L-shaped Barrington Medical Building, West Los Angeles, CA. Shear cracking in the perimeter frames undermined the column strength enough at some levels that the windows buckled due to a decreased column/story height. [5]

Year	Units	Concrete Compressive Strength Ranges for Various Periods			
		Footings	Beams	Slabs	Columns
1900-1913	psi	1000 - 2000	2000 - 3000	1000 - 2000	1000 - 2000
	MPa	14 - 28	28 - 42	14 - 28	14 - 28
1920-1943	psi	1000 - 3000	2000 - 5000	2000 - 3000	2000 - 3000
	MPa	14 - 42	28 - 70	28 - 42	28 - 42
1950-1963	psi	2000 - 3000	3000 - 4000	3000 - 4000	3000 - 4000
	MPa	28 - 42	42 - 56	42 - 56	42 - 56
1970-Present	psi	3000 - 4000	3000 - 5000	3000 - 5000	3000 - 5000
	MPa	42 - 56	42 - 70	42 - 70	42 - 70

Figure 27: Table of Concrete Compression Strength for various time periods. Adapted from Fema 356. [7]

Year	Units	Structural		Intermediate			Hard	
		grade 33	grade 40	grade 50	grade 60	grade 75		
1911-1959	ksi	33	40	50	60	75		
	MPa	228	276	345	414	517		
1959-1968	ksi	33	40	50	60	75		
	MPa	228	276	345	414	517		
1968-1974	ksi	40	50	60				
	MPa	276	345	414				

Figure 28: Table of Steel Reinforcement Bar Tensile Strength for various time periods. Adapted from Fema 356. [7]




Figure 29: Typical capacity curve showing building performance levels. [1]




Figure 30: Plan of retrofit design for Holiday Inn, Van Nuys, CA. [1]




Figure 31: Elevation of retrofit design for Holiday Inn, Van Nuys, CA showing new moment frames to be added. [1]




Figure 32: Detail of retrofit design for Holiday Inn, Van Nuys, CA showing connection of new moment frame beam to old moment frame beam. [1]




Figure 33: Detail of retrofit design for Holiday Inn, Van Nuys, CA showing connection of new moment frame column to old moment frame column. [1]

Table 6-1. Checklist of Retrofit Design Considerations

Constraint	Importance (1-10)	Limitation
Performance objective	—	Structural Level _____ for _____ % in 50 years Nonstructural Level _____ for _____ % in 50 years
Project cost	—	Constr: \$ _____ Other: \$ _____
Project schedule	—	_____ months
Construction occupancy	—	_____ Building vacant _____ Partial occupancy _____ Full occupancy
Hazardous materials	—	_____ none known _____ known present _____ intended remediation
Building appearance	—	_____ May be altered _____ Must be preserved
Floor space impact	—	_____ No obstruction _____ Obstruction allowed

Figure 34: Checklist of Retrofit Design Considerations to help determine the importance of various items for a project. [1]

Table 6-2. Sample Strategy Evaluation Matrix

Strategy	Desirability					Final Score	Comments
	Cost	Schedule	Architectural Impact	Occupancy Disruption	Seismic Performance		
Importance (1-10, 10 = most important)	10	3	7	3	10		
System completion	0	0	0	0	0	0	Not viable
System strengthening and stiffening							
Exterior shear walls	3	10	7	10	6	259	
Exterior braced frames	10	9	3	10	5	228	
Interior shear walls	7	8	10	0	6	224	
Interior braced frames	8	7	10	0	3	221	
Exterior outriggers	3	10	3	10	6	231	
Demand reduction							
Base isolation	3	5	10	0	10	215	
Enhanced damping	0	0	0	0	0	0	Not viable
Mass reduction	0	0	0	0	0	0	Not viable

Figure 35: Sample Retrofit Strategy Evaluation Matrix. The table evaluates the relative merits of each structural retrofit strategy. Ratings range from 1 to 10 with 10 representing little impact or the most desirable effect and 1 representing the least

2. Architectural Aspects

2.1 Siting

These buildings are typically found in flat terrain. They do not share common walls with adjacent buildings. The separation distance varies considerably depending on the location of the building. When separated from adjacent buildings, the typical distance from a neighboring building is 5 meters.

2.2 Building Configuration

Openings make up approximately 20-35% of the total wall area. Dimensions of the openings vary between 0.5 meters and 4 meters.

2.3 Functional Planning

The main function of this building typology is mixed use (both commercial and residential use). Some buildings may have a commercial ground floor with residential housing on the upper floors, yet most are full residential. In a typical building of this type, there are no elevators and 1-2 fire-protected exit staircases. Staircase is used for escape instead of elevator. Multiple staircases are sometimes available. Staircases are sometimes attached to the side of the building.

2.4 Modification to Building

Most buildings of this type are rectangular, or nearly rectangular, but different building configurations can be found including L-shaped and U-shaped.

3. Structural Details

3.1 Structural System

Material	Type of Load-Bearing Structure	#	Subtypes	Most appropriate type
	Stone Masonry Walls	1	Rubble stone (field stone) in mud/lime mortar or without mortar (usually with timber roof)	<input type="checkbox"/>
		2	Dressed stone masonry (in lime/cement mortar)	<input type="checkbox"/>

Masonry	Adobe/ Earthen Walls	3	Mud walls	<input type="checkbox"/>	
		4	Mud walls with horizontal wood elements	<input type="checkbox"/>	
		5	Adobe block walls	<input type="checkbox"/>	
		6	Rammed earth/Pise construction	<input type="checkbox"/>	
	Unreinforced masonry walls	7	Brick masonry in mud/lime mortar	<input type="checkbox"/>	
		8	Brick masonry in mud/lime mortar with vertical posts	<input type="checkbox"/>	
		9	Brick masonry in lime/cement mortar	<input type="checkbox"/>	
		10	Concrete block masonry in cement mortar	<input type="checkbox"/>	
	Confined masonry	11	Clay brick/tile masonry, with wooden posts and beams	<input type="checkbox"/>	
		12	Clay brick masonry, with concrete posts/tie columns and beams	<input type="checkbox"/>	
		13	Concrete blocks, tie columns and beams	<input type="checkbox"/>	
	Reinforced masonry	14	Stone masonry in cement mortar	<input type="checkbox"/>	
		15	Clay brick masonry in cement mortar	<input type="checkbox"/>	
		16	Concrete block masonry in cement mortar	<input type="checkbox"/>	
	Structural concrete	Moment resisting frame	17	Flat slab structure	<input type="checkbox"/>
			18	Designed for gravity loads only, with URM infill walls	<input checked="" type="checkbox"/>
19			Designed for seismic effects, with URM infill walls	<input type="checkbox"/>	
20			Designed for seismic effects, with structural infill walls	<input type="checkbox"/>	
21			Dual system – Frame with shear wall	<input type="checkbox"/>	
Structural wall		22	Moment frame with in-situ shear walls	<input type="checkbox"/>	
		23	Moment frame with precast shear walls	<input type="checkbox"/>	
Precast concrete		24	Moment frame	<input type="checkbox"/>	
		25	Prestressed moment frame with shear walls	<input type="checkbox"/>	
		26	Large panel precast walls	<input type="checkbox"/>	
	27	Shear wall structure with walls cast-in-situ	<input type="checkbox"/>		
	28	Shear wall structure with precast wall panel structure	<input type="checkbox"/>		
Steel	Moment-resisting frame	29	With brick masonry partitions	<input type="checkbox"/>	
		30	With cast in-situ concrete walls	<input type="checkbox"/>	
		31	With lightweight partitions	<input type="checkbox"/>	
	Braced frame	32	Concentric connections in all panels	<input type="checkbox"/>	
		33	Eccentric connections in a few panels	<input type="checkbox"/>	
	Structural wall	34	Bolted plate	<input type="checkbox"/>	
35		Welded plate	<input type="checkbox"/>		
		36	Thatch	<input type="checkbox"/>	
		37	Walls with bamboo/reed mesh and post (Wattle and Daub)	<input type="checkbox"/>	
		38	Masonry with horizontal beams/planks at intermediate levels	<input type="checkbox"/>	

Timber	Load-bearing timber frame	39	Post and beam frame (no special connections)	<input type="checkbox"/>
		40	Wood frame (with special connections)	<input type="checkbox"/>
		41	Stud-wall frame with plywood/gypsum board sheathing	<input type="checkbox"/>
		42	Wooden panel walls	<input type="checkbox"/>
Other	Seismic protection systems	43	Building protected with base-isolation systems	<input type="checkbox"/>
		44	Building protected with seismic dampers	<input type="checkbox"/>
	Hybrid systems	45	other (described below)	<input type="checkbox"/>

3.2 Gravity Load-Resisting System

The vertical load-resisting system is reinforced concrete moment resisting frame. Vertical load-carrying frames carry the gravity loads in addition to the moment frames which share some of the gravity loads. The gravity frames may or may not include beams, depending on the type of roof/floor diaphragm system. Whether there are complete frames or just columns, the columns for this type of system are usually laid out in a regular grid pattern. The gravity loads are transferred to the frames/columns by monolithically cast concrete floor and roof slab systems. Various concrete floor and roof framing systems used with this building type include flat plate, pan joist or beam, one-way slab and two-way slabs or waffle slabs. The gravity load system will experience similar displacements as the lateral load carrying elements during seismic activity so it should not be considered entirely separated from the lateral system. Sometimes, even flat slab structures are adopted.

3.3 Lateral Load-Resisting System

The lateral load-resisting system is reinforced concrete moment resisting frame. Concrete moment-resisting frames are monolithically cast systems of beams and columns that resist lateral loads through bending of the frame members. Most concrete frame buildings include interior beam-column frames as well as exterior pier-spandrel frames, which act together to resist seismic loads. The difference in the interior and exterior frames is mainly that the exterior frame spandrel beams have deeper dimensions than the interior beams. Many buildings will have lateral force resisting frames only along the perimeter of the structure so the interior frames are primarily used to resist gravity loads. The concrete frames were designed to provide enough strength to resist code-specified lateral forces at the time of their construction yet were not designed or detailed for ductile performance once the frame elements exhibited inelastic behavior. For this reason, these pre-1976 frames are also called non-ductile moment-resisting frames (Figures 1 - 5, 22). In reality, they have a highly variable degree of ductility. Sometimes, even flat slab structures are adopted.

3.4 Building Dimensions

The typical plan dimensions of these buildings are: lengths between 30 and 45 meters, and widths between 15 and 30 meters. The building has 4 to 15 storey(s). The typical span of the roofing/flooring system is 4.0 - 8.0 meters. The typical storey height in such buildings is 3 meters. The typical structural wall density is none.

3.5 Floor and Roof System

Material	Description of floor/roof system	Most appropriate floor	Most appropriate roof
Masonry	Vaulted	<input type="checkbox"/>	<input type="checkbox"/>
	Composite system of concrete joists and masonry panels	<input type="checkbox"/>	<input type="checkbox"/>
	Solid slabs (cast-in-place)	<input type="checkbox"/>	<input type="checkbox"/>
	Waffle slabs (cast-in-place)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
	Flat slabs (cast-in-place)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
	Precast joist system	<input type="checkbox"/>	<input type="checkbox"/>

Structural concrete	Hollow core slab (precast)	<input type="checkbox"/>	<input type="checkbox"/>
	Solid slabs (precast)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
	Beams and planks (precast) with concrete topping (cast-in-situ)	<input type="checkbox"/>	<input type="checkbox"/>
	Slabs (post-tensioned)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Steel	Composite steel deck with concrete slab (cast-in-situ)	<input type="checkbox"/>	<input type="checkbox"/>
Timber	Rammed earth with ballast and concrete or plaster finishing	<input type="checkbox"/>	<input type="checkbox"/>
	Wood planks or beams with ballast and concrete or plaster finishing	<input type="checkbox"/>	<input type="checkbox"/>
	Thatched roof supported on wood purlins	<input type="checkbox"/>	<input type="checkbox"/>
	Wood shingle roof	<input type="checkbox"/>	<input type="checkbox"/>
	Wood planks or beams that support clay tiles	<input type="checkbox"/>	<input type="checkbox"/>
	Wood planks or beams supporting natural stones slates	<input type="checkbox"/>	<input type="checkbox"/>
	Wood planks or beams that support slate, metal, asbestos-cement or plastic corrugated sheets or tiles	<input type="checkbox"/>	<input type="checkbox"/>
	Wood plank, plywood or manufactured wood panels on joists supported by beams or walls	<input type="checkbox"/>	<input type="checkbox"/>
Other	Described below	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

3.6 Foundation

Type	Description	Most appropriate type
Shallow foundation	Wall or column embedded in soil, without footing	<input type="checkbox"/>
	Rubble stone, fieldstone isolated footing	<input type="checkbox"/>
	Rubble stone, fieldstone strip footing	<input type="checkbox"/>
	Reinforced-concrete isolated footing	<input checked="" type="checkbox"/>
	Reinforced-concrete strip footing	<input checked="" type="checkbox"/>
	Mat foundation	<input type="checkbox"/>
	No foundation	<input type="checkbox"/>
Deep foundation	Reinforced-concrete bearing piles	<input checked="" type="checkbox"/>
	Reinforced-concrete skin friction piles	<input type="checkbox"/>
	Steel bearing piles	<input type="checkbox"/>
	Steel skin friction piles	<input type="checkbox"/>
	Wood piles	<input type="checkbox"/>
	Cast-in-place concrete piers	<input checked="" type="checkbox"/>
	Caissons	<input type="checkbox"/>
Other	Described below	<input type="checkbox"/>

It consists of reinforced concrete end-bearing piles and cast in-place reinforced concrete piers.

4. Socio-Economic Aspects

4.1 Number of Housing Units and Inhabitants

Each building typically has 51-100 housing unit(s). Usually, there are 20-70 units in each building. The number of inhabitants in a building during the day or business hours is more than 20. The number of inhabitants during the evening and night is more than 20.

4.2 Patterns of Occupancy

Usually, one family lives in each housing unit.

4.3 Economic Level of Inhabitants

Income class	Most appropriate type
a) very low-income class (very poor)	<input checked="" type="checkbox"/>
b) low-income class (poor)	<input checked="" type="checkbox"/>
c) middle-income class	<input checked="" type="checkbox"/>
d) high-income class (rich)	<input checked="" type="checkbox"/>

Some low income housing units are built with this type. Other buildings are in urban middle-class areas.

Ratio of housing unit price to annual income	Most appropriate type
5:1 or worse	<input type="checkbox"/>
4:1	<input type="checkbox"/>
3:1	<input type="checkbox"/>
1:1 or better	<input checked="" type="checkbox"/>

What is a typical source of financing for buildings of this type?	Most appropriate type
Owner financed	<input checked="" type="checkbox"/>
Personal savings	<input type="checkbox"/>
Informal network: friends and relatives	<input type="checkbox"/>
Small lending institutions / micro-finance institutions	<input type="checkbox"/>
Commercial banks/mortgages	<input checked="" type="checkbox"/>
Employers	<input type="checkbox"/>
Investment pools	<input type="checkbox"/>
Government-owned housing	<input checked="" type="checkbox"/>
Combination (explain below)	<input type="checkbox"/>
other (explain below)	<input type="checkbox"/>

In each housing unit, there are 1 bathroom(s) without toilet(s), no toilet(s) only and 1 bathroom(s) including toilet(s).

4.4 Ownership

The type of ownership or occupancy is renting and individual ownership.

Type of ownership or occupancy?	Most appropriate type
Renting	<input checked="" type="checkbox"/>

outright ownership	<input type="checkbox"/>
Ownership with debt (mortgage or other)	<input type="checkbox"/>
Individual ownership	<input checked="" type="checkbox"/>
Ownership by a group or pool of persons	<input type="checkbox"/>
Long-term lease	<input type="checkbox"/>
other (explain below)	<input type="checkbox"/>

5. Seismic Vulnerability

5.1 Structural and Architectural Features

Structural/ Architectural Feature	Statement	Most appropriate type		
		Yes	No	N/A
Lateral load path	The structure contains a complete load path for seismic force effects from any horizontal direction that serves to transfer inertial forces from the building to the foundation.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Building Configuration	The building is regular with regards to both the plan and the elevation.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Roof construction	The roof diaphragm is considered to be rigid and it is expected that the roof structure will maintain its integrity, i.e. shape and form, during an earthquake of intensity expected in this area.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Floor construction	The floor diaphragm(s) are considered to be rigid and it is expected that the floor structure(s) will maintain its integrity during an earthquake of intensity expected in this area.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Foundation performance	There is no evidence of excessive foundation movement (e.g. settlement) that would affect the integrity or performance of the structure in an earthquake.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Wall and frame structures-redundancy	The number of lines of walls or frames in each principal direction is greater than or equal to 2.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Wall proportions	Height-to-thickness ratio of the shear walls at each floor level is: Less than 25 (concrete walls); Less than 30 (reinforced masonry walls); Less than 13 (unreinforced masonry walls);	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Foundation-wall connection	Vertical load-bearing elements (columns, walls) are attached to the foundations; concrete columns and walls are doweled into the foundation.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Wall-roof connections	Exterior walls are anchored for out-of-plane seismic effects at each diaphragm level with metal anchors or straps	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Wall openings	The total width of door and window openings in a wall is: For brick masonry construction in cement mortar : less than 1/2 of the distance between the adjacent cross walls; For adobe masonry, stone masonry and brick masonry in mud mortar: less than 1/3 of the distance between the adjacent cross walls; For precast concrete wall structures: less than 3/4 of	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

	the length of a perimeter wall.			
Quality of building materials	Quality of building materials is considered to be adequate per the requirements of national codes and standards (an estimate).	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Quality of workmanship	Quality of workmanship (based on visual inspection of few typical buildings) is considered to be good (per local construction standards).	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Maintenance	Buildings of this type are generally well maintained and there are no visible signs of deterioration of building elements (concrete, steel, timber)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Additional Comments				

5.2 Seismic Features

Structural Element	Seismic Deficiency	Earthquake Resilient Features	Earthquake Damage Patterns
Walls	The column deficiencies include (a) Tie configuration with 90 degree hooks, (b) Tie spacing too large to provide adequate confinement, (c) Lap splice location above floor slab at region of high moment, (d) Lap splice length too short to provide force transfer, and (e) Tie spacing at lap splice too large. The beam deficiencies include (a) Transverse shear ties are not closed and have 90 degree hooks, (b) Transverse shear tie spacing is too large, (c) Transverse shear ties are sized for gravity loads only and are too small, (d) Transverse shear ties missing at mid-span of beams, (e) Top longitudinal steel reinforcement is discontinuous at the beam center so it can not account for seismic bending or reversals, (e) Bottom longitudinal steel reinforcement is often discontinuous at the column faces or laps only slightly within the beam-column joint, and (f) Longitudinal steel reinforcement at end frames terminates without hooks or with hooks that bend away from the joint so it provides inadequate development length and continuity. The frame deficiencies include (a) Weak column/strong beam characteristics make floors vulnerable to collapse from failed columns, (b) Shear capacity is less than what is required to form plastic hinges for both columns and beam, (c) Beam-column joint has inadequate shear capacity, (d) Beam-column joint has inadequate confinement, (e) Beams often frame eccentrically to the columns, (f) No bottom slab reinforcement passes through column reinforcement cage in interior flat slab/column frames, and (g) gravity systems are too rigid and have inadequate deformation compatibility with the lateral system.	The frames Will not resist substantial lateral loads without damage but must maintain gravity loads.	The columns damage patterns include (a) Shear (X) cracking, especially in perimeter frames with deep spandrel beams which incurs short column effects (Figures 24,25 & 26), (b) Column spalling and buckling of the longitudinal steel from inadequate confinement, resulting in undermined compressive strength of the concrete core (Figure 23 & 14), (c) Crushing failure at top and/or bottom of column (Figure 20, 21 & 17), (d) Column failure at base due to high shear at the lap splice region, and (f) 90 degree hooks pop-out, cause spalling and undermine the strength of the concrete core. The beam damage patterns include (a) 45 degree shear cracking generating from beam ends because of insufficient stirrups (Figures 6 & 7), (b) Concrete crushing at column face, (c) End beam to pull out/separate from the last column in frame due to large drifts and inadequate bar hooks and development, and (d) 90 degree hooks pop-out, cause spalling and undermine the strength of the concrete core. The frame damage patterns include (a) Permanent column side sway /story drift (Figure 12), (b) Beam-column joint shear cracking and concrete disintegration especially in interior frames without deep beams (Figures 8 & 9), (c) Localized column failures/column collapse at weak or soft story locations (Figures 10, 11 & 20), (d) Beam pullout from joints due to moment reversals when beam bottom bars are spliced in the center of the joint for only small distances, (e) Punching shear failure of interior columns particularly in flat slab/column frames, (f) Column hinging and failure due to strong beam/weak column design, and (g) gravity systems damaged from lateral deformations due to their rigidity.
Frame (Columns, beams)	COLUMN DEFICIENCIES: --Tie configuration with 90 degree hooks. --Tie spacing too large to provide adequate confinement. --Lap splice location above floor slab at region of high moment. --Lap splice length too short to provide force transfer. --Tie spacing at lap splice too large. BEAM DEFICIENCIES: --Transverse shear ties are not closed and have 90 degree hooks. --Transverse shear tie spacing is too large. --Transverse shear ties are sized for gravity loads only and are too small. --Transverse shear ties missing at mid-span of beams. --Top longitudinal steel reinforcement is discontinuous at the beam center so it can not account for seismic bending or reversals. --Bottom longitudinal steel reinforcement is often discontinuous at the column faces or laps only slightly within the beam-column joint. --Longitudinal steel reinforcement at end frames terminates without hooks or with hooks that bend away from the joint so it provides inadequate development length and continuity. FRAME DEFICIENCIES: --Weak column/strong beam characteristics make floors vulnerable to collapse from failed columns. --Shear capacity is less than what is required to form plastic hinges for	FRAMES: --Will not resist substantial lateral loads without damage but must maintain gravity loads.	COLUMN DAMAGE PATTERNS: --Shear (X) cracking, especially in perimeter frames with deep spandrel beams which incurs short column effects (Figures 24,25 & 26). --Column spalling and buckling of the longitudinal steel from inadequate confinement, resulting in undermined compressive strength of the concrete core (Figure 23 & 14). --Crushing failure at top and/or bottom of column (Figure 20, 21 & 17). --Column failure at base due to high shear at the lap splice region. --90 degree hooks pop-out, cause spalling and undermine the strength of the concrete core. BEAM DAMAGE PATTERNS: --45 degree shear cracking generating from beam ends because of insufficient stirrups (Figures 6 & 7). --Concrete crushing at column face. --End beam to pull out/separate from the last column in frame due to large drifts and inadequate bar hooks and development. --90 degree hooks pop-out, cause spalling and undermine the strength of the concrete core. FRAME DAMAGE PATTERNS: --Permanent column side sway /story drift (Figure 12). --Beam-column joint

	both columns and beam. --Beam-column joint has inadequate shear capacity. --Beam-column joint has inadequate confinement. --Beams often frame eccentrically to the columns. --No bottom slab reinforcement passes through column reinforcement cage in interior flat slab/column frames. --gravity systems are too rigid and have inadequate deformation compatibility with the lateral system		shear cracking and concrete disintegration especially in interior frames without deep beams (Figures 8 & 9). -- Localized column failures/column collapse at weak or soft story locations (Figures 10, 11 & 20). --Beam pullout from joints due to moment reversals when beam bottom bars are spliced in the center of the joint for only small distances. --Punching shear failure of interior columns particularly in flat slab/column frames. --Column hinging and failure due to strong beam/weak column design. -- gravity systems damaged from lateral deformations due to their rigidity.
Roof and floors	The slab deficiencies include (a) drag struts not provided at re-entrant corners, (b) insufficient detailing at diaphragm openings, and (c) slabs doweled into frames without hooks so the dowels are insufficient to develop yield strength or ultimate strength of diaphragms.	Slabs may be sufficient to handle corner stresses.	The earthquake damage pattern in slabs includes (a) punching shear failure at columns, and (b) 45 degree cracks propagating at openings and re-entrant corners.

Infill wall behavior is a problem if the walls have not been designed either to resist lateral loads as shear walls or to allow the frames alone to resist lateral loads. If an inadequate construction gap is provided around the infill walls, the deflection in the frames may cause the walls to interact with the frames, thereby stiffening the system as the wall acts as a compression strut or brace for the frame. This may be an advantage for a non-ductile frame design that would not perform well with large inter-story drifts but, when the walls act more like shear walls, problems result at wall discontinuities. When the infill walls are not solid or do not extend to the full height of the columns, they may induce short column/captive column failures. In this case, infill walls prohibit frames from responding properly. For many pre-1976 structures, these infill walls were placed throughout the building without seismic behavior in mind. As a result these infill walls often induce torsion in the structure or cause stress concentrations on elements that were not designed for large seismic loads due to wall discontinuities. In addition, infill walls are also a nonstructural hazard because they are prone to collapse when damaged.

5.3 Overall Seismic Vulnerability Rating

The overall rating of the seismic vulnerability of the housing type is B: MEDIUM-HIGH VULNERABILITY (i.e., poor seismic performance), the lower bound (i.e., the worst possible) is A: HIGH VULNERABILITY (i.e., very poor seismic performance), and the upper bound (i.e., the best possible) is C: MEDIUM VULNERABILITY (i.e., moderate seismic performance).

Vulnerability	high	medium-high	medium	medium-low	low	very low
	very poor	poor	moderate	good	very good	excellent
Vulnerability Class	A	B	C	D	E	F
	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

5.4 History of Past Earthquakes

Date	Epicenter, region	Magnitude	Max. Intensity
1971	San Fernando, CA	6.6	
1979	Imperial Valley, CA	6.4	
1989	Loma Prieta, CA	7.1	MMI X
1994	Northridge, CA	6.7	MMI IX

1964 Prince William Sound, Alaska M9.2 moment magnitude (8.4-8.6 richter magnitude) MMI XI. This earthquake is the second largest earthquake ever recorded, second only to the 1960 Chile earthquake with Mw = 9.5. (a) The 1964 Alaska earthquake damage demonstrated the need for designing buildings with more attention to their behavior during earthquakes. As a result of this earthquake, the American engineering community realized the need to design

buildings accounting for ductile behavior. (b) Two example buildings damaged in the 1964 Alaska earthquake demonstrate the vulnerability of concrete structures without ductile detailing. Although they are not all moment frame buildings, they demonstrate the important lessons learned from the earthquake. The 14-story reinforced concrete L Street Apartment building in Anchorage, Alaska used a series of slender walls connected with short spandrel girders to resist lateral loads. Characteristic x-shaped shear cracks in the girders showed that the girders were not properly designed to resist shear demands (Figures 6 & 7). West Anchorage High School in Anchorage, Alaska was a 2-story concrete frame building with shear walls that showed extreme damage. Failures were present in its beam-column joints, columns, shear walls and roof diaphragm (Figures 8 & 9). (c) After the 1971 San Fernando earthquake, the engineering community realized that more seismic detailing would be necessary for concrete buildings. The damage and subsequent research from this earthquake inspired key changes to code design requirements for concrete moment frame buildings. (d) Several main buildings highlighted the vulnerability of reinforced concrete design following the current building code in the San Fernando earthquake. Olive View Medical Center experienced damage in many of its buildings. The Olive View Psychiatric Day Care Center was a two-story moment frame building whose bottom story columns failed and caused the collapse of the complete lower story (Figure 10). The Olive View Hospital experienced great damage as well (Figures 11-12). The main issues related to moment frame design from this building are in regard to column detailing. General views of the hospital building show distortions of the first story columns, which were of two designs (Figure 13). The twelve corner columns were L-shaped with six ties (No. 3's at 18 inches) spaced over the story height (Figure 14). These columns completely shattered. The other 152 columns in the building had spiral steel ties (5/8 in. at 2-1/4 in. spacing) and although they lost much of their concrete covering, they retained load-carrying capacity (Figures 15 - 17). The ability of the spirally-reinforced columns to maintain vertical load carrying capability with such large horizontal drift demonstrates the advantage of detailing concrete for ductile behavior. These spiral columns would have been helped even more by the placement of all longitudinal steel within the spirals. Figure 13 shows the detail of the spiral column with its longitudinal steel within the steel spiral yet the damage images shows some rebar on the exterior of the spirals (Figures 15 & 16). While much of the major building damage was restricted to the first floor columns, there were shear failures in some of the upper story columns. Also many of the connections were damaged. Another concrete frame structure with non-ductile design was the San Fernando Veterans Administration Hospital, which was built in 1925. It consisted of concrete frames, concrete floors and hollow tile walls. This building suffered complete collapse (Figure 18).

6. Construction

6.1 Building Materials

Structural element	Building material	Characteristic strength	Mix proportions/ dimensions	Comments
Walls	Concrete and steel reinforcement are used.	The characteristic strengths of concrete and steel reinforcement are 20 MPa and 275 MPa, respectively.		See Figures 27 & 28, adapted from FEMA 356 which show the compressive strengths for concrete based on its use and time of construction. The figures also show similar data for the tensile strengths of the reinforcing based on the era of construction.
Foundation	Concrete and steel reinforcement are used.	The characteristic strengths of concrete and steel reinforcement are 17 MPa and 275 MPa, respectively.		
Frames (beams & columns)	Concrete and steel reinforcement are used.	The characteristic strengths of concrete and steel reinforcement are 17 MPa and 275 MPa, respectively.		See Figures 27 & 28, adapted from FEMA 356 which show the compressive strengths for concrete based on its use and time of construction. The figures also show similar data for the tensile strengths of the reinforcing based on the era of construction.
Roof and floor(s)	Concrete and steel reinforcement are used.	The characteristic strengths of concrete and steel reinforcement are 17 MPa and 275 MPa, respectively.		

6.2 Builder

This building type is built by contractors for a developer. Builders do not typically live in this construction type.

6.3 Construction Process, Problems and Phasing

This type of non-ductile construction is no longer permitted to be built in seismic regions of the USA. The construction process for current buildings is discussed below and is comparable to pre-1976 concrete structures. Mechanical equipment is used for most of the construction process. Human-operated machines are used to excavate the site, dig the foundations, lift and place heavy building elements. Formwork is primarily made of wood except for unique areas that may need alternative solutions, which is rare (i.e. hill foundations where driven piles may be used to make the formwork for a basement retaining wall). Most reinforcement is ordered and delivered from steel companies in the sizes required from the design drawings and is ordered by the contractor based on the design drawings. Most of the reinforcement with required bends and hooks are ordered so that these modifications will be done in the steel factory to maintain uniform dimensions throughout the project. Some reinforcing may also be bent in the field. Most reinforcing cages for columns and beams are hand-tied in the field. Concrete is typically transported via concrete trucks pre-mixed and hydrated from a batch plant to maintain the consistency of the concrete throughout the building. The concrete is either pumped or poured from the trucks into the desired formwork. Trucks deliver concrete continuously so that each segment of the structure is built in monolithic segments. Samples from each concrete truck are tested to ensure adequate strength. If any concrete batch is of insufficient strength (which rarely happens) that portion of the structure must be removed or retrofitted until it conforms to the desired standards. The main building contractor may hire various other construction crews for specialty areas of the construction. This is called subcontracting and is done depending on the size and complexity of the project. Parts of the building construction that may be subcontracted include the roofing, reinforcing layout and mechanical/electrical systems. The construction of this type of housing takes place in a single phase. Typically, the building is originally designed for its final constructed size. In the USA, many different companies / entities are involved in the design and construction of a building including architects, engineers (structural, mechanical, electrical, heating/air systems, elevator), contractors, various subcontractors and government planning/inspection agencies. Due to the high number of entities involved, delays in construction are common.

6.4 Design and Construction Expertise

All engineers and architects must be licensed by each state where they do work. Licensing requirements vary from state to state especially depending on the degree of seismic activity or other natural phenomena that require special design approaches. Most states require passing an exam and logging a particular number of years working under a licensed engineer or architect depending on the amount of education of the applicant. Licensed engineers and architects generally work in a design firm where they supervise unlicensed engineers or architects who assist on projects. Only licensed engineer or architect can officially design a project so any errors are their responsibility. Construction companies run most construction projects for multi-story buildings. A construction manager who has many years of experience or has a university degree in construction management or both will head each project. This construction manager is in charge of making sure the project runs on schedule, on budget and meets the design requirements. The construction manager supervises all other managers and subcontractors who direct the laborers. Tasks are assigned to laborers according to skill level and expertise. The owner hires an architect, who in turn hires an engineer for the structural design and a contractor for the construction. A resident engineer is on site during construction for inspections.

6.5 Building Codes and Standards

This construction type is addressed by the codes/standards of the country. The Uniform Building Code (UBC) was the national code adopted by most of the states in the USA during the time of this non-ductile concrete moment frame construction type. Various cities and states have codes that further extend some sections of the UBC, in an attempt to adapt the code to regional specific issues and characteristics. Much of the text related to the design and behavior of concrete structures within the UBC and other city codes is based on the American Concrete Institute (ACI) 318 document: Building Code Requirements for Structural Concrete and Commentary. Although the ACI 318 is not a legally binding code by itself (unless it is adopted as a legal code by individual municipalities), the text is often copied directly into the UBC codes which are legally binding. The ACI and UBC codes are updated roughly every 3 years. All the ACI and UBC codes prior to 1976 had few requirements for ductile detailing, which makes all concrete moment frame buildings constructed prior to 1976 non-ductile moment resisting frames without seismic details. These nonductile requirements were the state-of-practice of the time. The year the first code/standard addressing this type of construction issued was This type of construction has not been allowed by the building code since the 1970's (depending on local adoption of the 1976 UBC). Prior to 1967, the Uniform Building Code (UBC) did not address seismic or ductile detailing. The 1964 Alaska earthquake damage demonstrated the need for designing buildings with more attention to their behavior during earthquakes. As a result the 1968 UBC was the first code to introduce some ductile detailing requirements. After the 1971 San Fernando earthquake, the engineering community realized that more seismic detailing would be necessary for concrete buildings. The 1976 UBC is considered to be the first "modern" building code for concrete moment frame construction due to its heightened seismic requirements. This building code increased the loads used for lateral design by adding a new soil factor and mandated new detailing requirements. All

buildings designed before this 1976 UBC are considered to have a non-ductile design. The most recent code/standard addressing this construction type issued was The current UBC and the new IBC (International Building Code) use performance-based design methods for concrete structures. These methods factor the demands on the structure to increase the values, then factor the capacity of the structure to underestimate the true capacity. With this strength design approach the artificially low building capacity must be greater than the artificially high demand on the building by seismic forces. The demand values for building design are based on two theoretical earthquakes. The two earthquakes most used are the 10% in 50 year probability (for most standard structures) and the 2% in 50 years probability (for critically important structures like hospitals). These mean that the buildings are designed to resist an earthquake large enough that the likelihood of it being exceeded is only 10% in 50 years which correlates to one large event in approximately 500 years. For the 2%/50 year this correlates to approximately a 2,500 year return. This insures that all buildings are designed to withstand moderate earthquakes with minimal damage. In addition, concrete buildings are designed with great ductility so while a building may be damaged in an earthquake, it will not collapse. The members and connections in the building are designed to deform inelastically and thereby absorb the earthquake energy in a prescribed manner that will prevent structural collapse. Keeping this in mind, the design is based on the type of performance desired from the building in an earthquake. Hospitals, for example, are designed so that they can withstand even great earthquakes without considerable damage or loss of function so that they may operate after the earthquake to care for the injured. This is called the Immediate Occupancy Performance Level. Typical office buildings, however, are not considered critical after a major earthquake and are designed to a level that prevents the building collapse and will ensure the safety of the building occupants while allowing the building to be damaged even beyond repair. This is called the Life Safety Performance Level. Most houses and housing projects are designed to the same performance level as office buildings. While any building can be designed to a higher level of performance, the cost of such design is generally too great to be practical, so most non-essential buildings are designed to preserve the lives of any inhabitants so that they may safely exit the building after the earthquake (Figure 29).

The Uniform Building Code (UBC) was the national code adopted by most of the states in the USA during the time of this non-ductile concrete moment frame construction type. Various cities and states have codes that further extend some sections of the UBC, in an attempt to adapt the code to regional specific issues and characteristics. Much of the text related to the design and behavior of concrete structures within the UBC and other city codes is based on the American Concrete Institute (ACI) 318 document: Building Code Requirements for Structural Concrete and Commentary. Although the ACI 318 is not a legally binding code by itself (unless it is adopted as a legal code by individual municipalities), the text is often copied directly into the UBC codes which are legally binding. The ACI and UBC codes are updated roughly every 3 years. All the ACI and UBC codes prior to 1976 had few requirements for ductile detailing, which makes all concrete moment frame buildings constructed prior to 1976 non-ductile moment resisting frames without seismic details. These nonductile requirements were the state-of-practice of the time. This type of construction has not been allowed by the building code since the 1970's (depending on local adoption of the 1976 UBC). Prior to 1967, the Uniform Building Code (UBC) did not address seismic or ductile detailing. The 1964 Alaska earthquake damage demonstrated the need for designing buildings with more attention to their behavior during earthquakes. As a result the 1968 UBC was the first code to introduce some ductile detailing requirements. After the 1971 San Fernando earthquake, the engineering community realized that more seismic detailing would be necessary for concrete buildings. The 1976 UBC is considered to be the first "modern" building code for concrete moment frame construction due to its heightened seismic requirements. This building code increased the loads used for lateral design by adding a new soil factor and mandated new detailing requirements. All buildings designed before this 1976 UBC are considered to have a non-ductile design. The current UBC and the new IBC (International Building Code) use performance-based design methods for concrete structures. These methods factor the demands on the structure to increase the values, then factor the capacity of the structure to underestimate the true capacity. With this strength design approach the artificially low building capacity must be greater than the artificially high demand on the building by seismic forces. The demand values for building design are based on two theoretical earthquakes. The two earthquakes most used are the 10% in 50 year probability (for most standard structures) and the 2% in 50 years probability (for critically important structures like hospitals). These mean that the buildings are designed to resist an earthquake large enough that the likelihood of it being exceeded is only 10% in 50 years which correlates to one large event in approximately 500 years. For the 2%/50 year this correlates to approximately a 2,500 year return. This insures that all buildings are designed to withstand moderate earthquakes with minimal damage. In addition, concrete buildings are designed with great ductility so while a building may be damaged in an earthquake, it will not collapse. The members and connections in the building are designed to deform inelastically and thereby absorb the earthquake energy in a prescribed manner that will prevent structural collapse. Keeping this in mind, the design is based on the type of performance desired from the building in an earthquake. Hospitals, for example, are designed so that they can withstand even great earthquakes without considerable damage or loss of function so that they may operate after the earthquake to care for the injured. This is called the Immediate Occupancy Performance Level. Typical office buildings, however, are not considered critical after a major earthquake and are designed to a level that prevents the building collapse and will ensure the safety of the building occupants while allowing the building to be damaged even beyond repair. This is called the Life Safety Performance Level. Most houses and housing projects are designed to the same performance level as office buildings. While any building can be designed to a higher level of performance, the cost of such design is generally too great to be practical, so most non-essential buildings are designed to preserve the lives of any inhabitants so that they may safely exit the building after the earthquake (Figure 29).

A professional engineer stamps all building drawings, certifying that they meet code requirements. In the field, the resident engineer inspects construction to ensure it conforms with the design drawings. Local building officials may also inspect during or after construction to ensure compliance with local codes.

6.6 Building Permits and Development Control Rules

This type of construction is an engineered, and authorized as per development control rules. Building permits are required to build this housing type.

6.7 Building Maintenance

Typically, the building of this housing type is maintained by Owner(s). The maintenance of buildings varies depending on the diligence of the owner.

6.8 Construction Economics

Total building cost is approximately \$200 - \$250 per square feet (\$2100 - \$ 2700 per square meter); Structural costs are approximately \$30 - \$50 per square feet (\$350 - \$ 550 per square meter).

7. Insurance

Earthquake insurance for this construction type is typically available. For seismically strengthened existing buildings or new buildings incorporating seismically resilient features, an insurance premium discount or more complete coverage is available. -- Earthquake insurance is widespread for commercial buildings along the west coast of the United States. [19] The premium is large, sometimes reaching over \$1 million per year for large buildings. With premiums this high, insurers can afford to inspect the building very thoroughly. There is an incentive for the building owners to spend money on mitigation (e.g., bracing walls, ceilings, storage tanks, etc., to qualify for insurance and to get a lower premium). In addition, commercial buildings are often built by the businesses that will occupy them and have a long-term view. Therefore, building owners may be willing to spend extra money at the time of construction for earthquake mitigation to protect the business and reduce future insurance costs. A business can deduct the cost of mitigation to the commercial building from taxes. There are generally more mitigation measures applicable to commercial structures and inventory than to homes. [21] -- For private homes in California, CEA (California Earthquake Authority) is the primary insurer. While this is not particularly applicable to concrete moment frame construction it gives a sense of the insurance environment in the United States. CEA is a privately funded and publicly managed state agency which provides earthquake coverage to renters and owners of residential property. CA law mandates that home owner's insurers and building insurers offer the option of earthquake coverage with their policy. This earthquake policy is generally a CEA policy offered through the insurer so it is CEA who pays the claims and collects the insurance premiums. Other CEA funding is by private investors and the insurers. [18, 20] Elsewhere in the United States, earthquake insurance is provided by private companies. The CEA has developed a loss prevention program that could ultimately make thousands of California homes more resistant to earthquake damage with a commitment by its Board to spend 5 percent of its investment income or up to \$5 million when feasible to loss mitigation programs. In 1999, the CEA sponsored a retrofit program in nine Bay area counties and received 15,000 calls as a result. Safety education and loss mitigation efforts continue. [20]. Earthquake insurance is widespread for commercial buildings along the west coast of the United States [19]. The premium is large, sometimes reaching over \$1 million per year for large buildings. Most policies cover physical damage and business interruption. [19] CEA deductibles are generally equal to 15% of the value of the home. Prior to the Northridge earthquake, deductibles were often 5% to 10%. [18] Premiums differ widely by location, insurer and the type of structure that is covered. Generally, older buildings cost more to insure than newer ones. Wood frame structures generally benefit from lower rates than brick buildings because they tend to withstand earthquake stresses better. Regions are graded on a scale of 1 to 5 for likelihood of earthquakes, and this may be reflected in insurance rates offered in those areas. The cost of earthquake insurance is calculated on "per \$1,000 basis." For instance, a frame house in the Pacific Northwest might cost between one to three dollars per \$1,000 worth of coverage, while it may cost less than fifty cents per \$1,000 on the East coast. [20].

8. Strengthening

8.1 Description of Seismic Strengthening Provisions

Strengthening of Existing Construction :

Seismic Deficiency	Description of Seismic Strengthening provisions used
Torsional problems (due to irregular architecture and/or an irregular structural system)	Insert an independent lateral load carrying system to relieve the existing frame or add additional members to make to structural system more regular and balanced.
Soft story	Insert additional members to supplement and stiffen the original frame system, i.e. construct new concrete shear walls or insert new steel braces or add new moment frame bays.
Weak columns--inadequate confinement and poor splices	Column jacketing with new reinforcement and concrete, fiber/polymer wrapping or steel jackets. Adding a concrete jacket also increases the cross sectional area of the column which helps increase its capacity.
Weak beams--inadequate transverse shear reinforcement	Epoxy injection of small to moderate cracks. Beam jacketing with new reinforcement and concrete or fiber/polymer wrapping
COMMENTS:	1. For independent systems, it is important that the new system is stiffer than the existing system so that it is engaged before the insufficient existing system.
COMMENTS:	2. Though this type of construction is no longer practiced in seismic regions, there are several issues associated with the retrofit construction for this type of building. Many aspects influence the type of retrofit chosen and the scale of the retrofit project. Any loss in revenue during retrofit construction is a critical issue for a building owner. Therefore retrofit designs must include alternatives that address the importance of many financial impacts. Some key decisions include whether it is of great importance to the owner to maintain constant access to the structure during the retrofit and the cost of removing tenants either temporarily or permanently during construction. The intrusiveness of the retrofit is also important as well as whether the scheme will reduce the value of the building by covering or removing windows, for example. Some retrofits may involve altering the architectural character of the building which must also included in the decision-making process. Finally the cost of various schemes should be included. It is important to keep in mind, however, that a higher material or labor cost for a scheme like polyfiber wrapping of columns may be a better choice due to minimal intrusion into the rentable space, the inconspicuousness of the retrofit and the speed of construction compared to concrete jacketing techniques. Figures 34 & 35 show a checklist and ranking system that can help a building owner to determine the best retrofit option for a particular building based on the owner's priorities.

DISCUSSION CONTINUED FROM SECTION 6.1 --Damage from the 1979 Imperial Valley earthquake demonstrated the need for better seismic detailing of concrete. The primary example of this was the Imperial County Services building, which displayed similar damage to the Olive View Hospital that was damaged in the San Fernando earthquake. This 6-story reinforced concrete frame and shear wall structure was completed in 1971 and was designed to be earthquake resistant. The building damage shows otherwise as the concrete columns at the ground floor experienced heavy damage that caused the building to sag by 30 cm (Figures 19 & 20). Inadequate confinement steel caused the longitudinal steel to buckle under the axial loading and the unconfined column core disintegrated under the shear and bending forces (Figure 21). --The 1989 Loma Prieta earthquake had approximately 10 seconds of strong shaking. Due to this short duration, fewer building structures experienced significant damage than in other earthquakes of comparable magnitude. Although there were many collapses of concrete bridges, roads and other infrastructure, few concrete buildings suffered total collapse or damage. --The 1994 Northridge earthquake caused extensive building damage throughout southern California. Concrete moment frames without seismic detailing were among the most susceptible building types and experienced vast amounts of damage and many collapses. Many of these buildings suffered due to inadequate strength but the main problem was their inadequate ductility. Brittle shear failures and other undesirable failure modes often dominated the building behavior and performance. --An example of reinforced concrete moment frame damage from the Northridge earthquake is the Holiday Inn in Van Nuys, CA. The Holiday Inn is a 7-story concrete flat slab building with perimeter frames built in 1966 whose lateral loads were

resisted by a combination of the interior column-slab frames and the exterior column-spandrel beam frames (Figures 1 - 3). Damage primarily consisted of shear failure of the columns and subsequent buckling of column vertical reinforcing between the ties where added confinement provided by the concrete cover was no longer available due to spalling (Figures 22 & 23). Minor to moderate shear cracks were observed in many beam-column joints at the lower stories. Several spandrel beams showed minor spalling as well as flexural cracks at the bottom of the beams, suggesting possible yielding of the bottom reinforcement. The building was red-tagged after the event and temporary shoring was placed in some bays where the vertical load carrying capacity was compromised. The Champaign Tower in Santa Monica, CA was a 15-story concrete building with nonductile moment frames in one-direction and shear walls in the other. Balcony parapets shortened the column spans, which induced short column effects on many columns in the lower stories as shown by the X-shaped shear cracking (Figures 24 & 25). Extensive coupling beam shear failures were evident in the building direction that had shear walls to resist the seismic loads. The Barrington Medical building was a 6-story, L-shaped reinforced concrete building built in the late 1960's. The lateral system included perimeter frames, shear walls along the interior core and shear walls at the perimeter. Shear cracking in the perimeter frame columns comprised most of the structural earthquake damage and undermined the column strength enough at some levels that the windows buckled due to a decreased column/story height (Figure 26).

8.2 Seismic Strengthening Adopted

Has seismic strengthening described in the above table been performed in design and construction practice, and if so, to what extent?

Many of these strengthening techniques have been applied to institutional buildings (i.e. universities) throughout California. The Holiday Inn in Van Nuys, CA which was damaged in the 1994 Northridge earthquake was retrofitted after the earthquake to repair the structure and improve its future earthquake performance. The method used for this structure was to insert new lateral load resisting elements to take the full seismic loads. New moment frames were added to the exterior of the building that were integrated with the existing frames (Figures 30 - 33). Although several of the buildings explained and documented in this report are hotels and office buildings, they have many similarities with non-ductile concrete apartment housing construction. Hotels, offices and typical housing structures have similar low story heights to maximize the number of floors throughout the height of the building. All of these uses also require the placement of many windows and openings throughout the structure. Large apartment buildings, offices and hotels may have a soft story at the lower level if there is a ground floor lobby or commercial space. Because of these similarities in building form, the seismic performance of these buildings is comparable. The hospitals used in this report document the reasons why the codes were changed so drastically in the 1970's. The failures in these hospitals also demonstrate deficiencies in design that commonly are seen in all moment frame buildings built before 1976.

Was the work done as a mitigation effort on an undamaged building, or as repair following an earthquake?

Strengthening is done both to repair damaged buildings and as a mitigation effort. After large earthquakes, owners of buildings outside of the earthquake region generally think about earthquake risks due to the evidence of destruction and loss in the media. Therefore, many buildings are retrofitted to current standards within a few years after a major earthquake while the dangers of earthquakes are fresh in the minds of the public. After that, concern about earthquake loss dwindles until another major earthquake inspires people to get prepared and protect their investments once again.

8.3 Construction and Performance of Seismic Strengthening

Was the construction inspected in the same manner as the new construction?

Yes.

Who performed the construction seismic retrofit measures: a contractor, or owner/user? Was an architect or engineer involved?

The engineer designed the retrofit.

What was the performance of retrofitted buildings of this type in subsequent earthquakes?

Several pre-1976 concrete frame buildings had been retrofitted prior to the 1994 Northridge earthquake. Most of these buildings performed well during the earthquake and suffered only minimal damage. Some UCLA campus residences had been retrofitted in 1981 to mitigate effects from potential column shear failure, lack of confinement in the columns, potential strong beam/weak column mechanism and potential column damage under the discontinuous shear walls by jacketing concrete moment-resisting frame columns and the lower level spandrels. New shear walls were

added below the discontinuous shear walls or the columns below the discontinuities were strengthened. These buildings demonstrated minimal damage after the Northridge earthquake. Another issue that had prompted retrofit prior to the Northridge earthquake was potential strong beam/weak column behavior. One documented building had been retrofitted to ensure that the beams and not the columns were the weakest link. The building had a post-tensioned slab with a column system that was intended to act as a moment frame. The retrofit added beams to the system, which would serve as the horizontal elements of the moment frame instead of the slab. These beams were designed so that they would yield before the columns once the system exhibited inelastic behavior. This building performed well in the Northridge earthquake and experienced no structural damage. Other pre-earthquake retrofit schemes included the installation of new shear walls and boundary elements.

Reference(s)

1. ATC 40: Seismic Evaluation and Retrofit of Concrete Buildings
ATC
Applied Technology Council 1996 1 and 2
2. Built to Resist Earthquakes: ATC/SEAOC Training Course
ATC, SEAOC & CSSC
Applied Technology Council, Structural Engineers Association
3. A Compendium of Background Reports on the Northridge Earthquake (January 17, 1994) for Executive Order W-78-94
CSSC
California Seismic Safety Commission 1994
4. Loma Prieta Earthquake Reconnaissance Report
EERI Spectra: The Professional Journal of EERI
Earthquake Engineering Research Institute, USA 1990
5. Northridge Earthquake Reconnaissance Report
Earthquake Spectra: The Professional Journal of EERI
Earthquake Engineering Research Institute (USA) 1996 2
6. FEMA 310: Handbook for the Seismic Evaluation of Buildings - A Prestandard
FEMA
Federal Emergency Management Agency 1998
7. FEMA 356: Prestandard and Commentary for the Seismic Rehabilitation of Buildings
FEMA
Federal Emergency Management Agency 2000
8. Engineering features of the San Fernando earthquake of February 9, 1971
Jennings, P.C.,
California Institute of Technology 1971 EERL-71-02
9. Earthquake Image Information System: Karl V. Steinbrugge Collection
NISEE
University of California, Berkeley
10. Earthquake Image Information System: William G. Godden Collection
NISEE
University of California, Berkeley
11. The Great Alaskan Earthquake and Tsunamis of 1964
Sokolowski, Thomas
NOAA
12. Performance Assessment for a Reinforced Concrete Frame Building
NEHRP
National Earthquake Hazards Reduction Program. 1998 VOL III-A

13. Special Moment Frames
Jack P. Moehle
SEAONC 2002
14. Prince William Sound, Alaska
USGS : Earthquakes Hazards Program
United States Geological Survey
15. ACI 318-02 : Building Code Requirements for Structural Concrete
ACI
American Concrete Institute, Farmington Hills, MI 2002
16. UBC 1997 - Uniform Building Code
ICBO
International Conference of Building Officials 2002
17. IBC 2000 : International Building Code
ICC
International Code Council 2000
18. California Creates State Earthquake Insurance Program
Natural Hazards Observer
Natural Hazards Res. & Appl. Information Center 1996 XXI, No.2
19. The Role of Insurance in Business Disaster Planning and Recovery
Claire Lee Reiss
Public Entity Risk Institute 2002
20. Earthquakes: Risk and Insurance Issues, The Topic
Insurance Information Institute, Inc. 2005
21. Earthquake Basics Brief #3. Insurance
EERI
Earthquake Engineering Research Institute (USA) 1997

Author(s)

1. Heidi Faison
Outreach Director, Pacific EQ Engineering Research Center, Univ of California Berkeley
325 Davis Hall--MC 1792, Berkeley, CA 94720, USA
Email:hfaison@berkeley.edu
2. Craig D. Comartin
President, C.D. Comartin Associates
7683 Andrea Avenue, Stockton CA 95207-1705, USA
Email:ccomartin@comartin.net FAX: (209) 472-7294
3. Kenneth Elwood
Assistant Professor, Dept. of Civil Engineering, University of British Columbia
2324 Main Mall Rm. 2010, Vancouver BC V6T 1Z4, CANADA
Email:elwood@civil.ubc.ca FAX: (604) 822-6901

Reviewer(s)

1. Mahmoud M. Hachem
, USA
Email:mhachem@wje.com
2. Ayhan Irfanoglu
Assistant Professor
School of Civil Engineering, Purdue University
W. Lafayette IN 47907, USA

Email:ayhan@purdue.edu FAX: 765-494-9886

Save page as

