
World Housing Encyclopedia

an Encyclopedia of Housing Construction in
Seismically Active Areas of the World



an initiative of
Earthquake Engineering Research Institute (EERI) and
International Association for Earthquake Engineering (IAEE)

HOUSING REPORT

Vivienda de Bahareque

| | |
|------------------|--|
| Report # | 141 |
| Report Date | 10-08-2007 |
| Country | EL SALVADOR |
| Housing Type | Timber Building |
| Housing Sub-Type | Timber Building : Walls with bamboo/reed mesh and post (Wattle and Daub) |
| Author(s) | Dominik Lang, Roberto Merlos, Lisa Holliday, Manuel A. Lopez M. |
| Reviewer(s) | Qaisar Ali |

Important

This encyclopedia contains information contributed by various earthquake engineering professionals around the world. All opinions, findings, conclusions & recommendations expressed herein are those of the various participants, and do not necessarily reflect the views of the Earthquake Engineering Research Institute, the International Association for Earthquake Engineering, the Engineering Information Foundation, John A. Martin & Associates, Inc. or the participants' organizations.

Summary

The bahareque construction type refers to a mixed timber, bamboo and mud wall construction technique which was the most frequently used method for simple houses in El Salvador before the 1965 earthquake (Levin, 1940; Yoshimura and Kuroki, 2001). According to statistics of the Vice-ministry of Housing and Urban Development in the year 1971 bahareque buildings had a share of 33.1 % of all buildings in El Salvador, while in 1994 the percentage of

bahareque declined to about 11 % (JSCE, 2001b) and in 2004 to about 5 % (9 % in rural areas; according to Dowling, 2004). The term 'bahareque' (also 'bajareque') has no precise equivalent in English, however in some Latin American countries this construction type is known as 'quincha' (engl.: wattle and daub). In order to prevent confusion it should be noted, that in El Salvador the term 'bahareque' is used for all types of this mixed construction type regardless the material of the horizontal elements (struts).

Bahareque buildings are characterized by high flexibility and elasticity when carefully constructed and well-maintained, and thus originally display good performance against dynamic earthquake loads. However, bahareque buildings in most cases show high vulnerability during earthquakes. This is caused by poor workmanship (carelessness and cost-cutting measures during construction), lack of maintenance (resulting in a rapid deterioration of building materials), and structural deficiencies such as a heavy roofing made out of tiles. Bahareque structures are primarily of residential use and only one story. The structural walls are mostly composed of vertical timber elements and horizontal struts which are either made of timber slats, cane/reed (carrizo), bamboo (vara de castilla, caña brava or caña de bambú) or tree limb (ramas). These members are generally 2- to 3-inches thick and are fastened at regularly spaced intervals from the base to ceiling height at the vertical elements (with nails, wires or vegetal fibers). This creates basketwork type skeleton which is then packed with mud and clay filler combined with chopped straws (or sometimes with whole canes), and covered with a plaster finish in some cases. In rural areas, the walls are often left plane, without any lime plaster and whitewash, or paint, which gives them a wavy surface with an unfinished character. It should be noted that bahareque houses in rural areas are quite different from those in urban areas both in terms of their esthetical appearance as well as their structural capacity (cf. Figures 1 and 2).

1. General Information

Buildings of this construction type can be found in many places throughout the country. However, the percentage of these buildings is higher in rural areas than urban areas. This type of housing construction is commonly found in both rural and urban areas.

Even though the basic construction technique is the same, there are differences between bahareque buildings found in urban and rural areas. Those found in urban areas are more stable and have more substantial construction, complete with (adobe-based or lime-based) plaster, and whitewash or paint (Figure 4), while those in rural regions appear to be temporary shacks reflecting a lower income level (Figure 3).

This construction type has been in practice for more than 200 years.

Currently, this type of construction is being built. However, only in rural areas. In urban areas it is not used anymore and the remaining bahareque dwellings from earlier days are oftentimes abandoned and derelict.



Figure 1. Typical bahareque building for rural areas.



Figure 3. Typical bahareque buildings in rural areas.

[Click to enlarge figures]

Figure 2. Typical bahareque building for urban areas.



Figure 4. Typical bahareque buildings in urban areas.

2. Architectural Aspects

2.1 Siting

These buildings are typically found in flat terrain. They do not share common walls with adjacent buildings. When separated from adjacent buildings, the typical distance from a neighboring building is variable, from cm to meters.

2.2 Building Configuration

The typical shape of the building plan for this housing type is rectangular. Figures 5 to 9 illustrate the plans, cross-sections and views of typical bahareque houses as can be found in rural areas. These representations are buildings from Guatemala since comparable information is hard to find for El Salvador. However, the structural details of bahareque buildings in El Salvador and Guatemala are comparable. The doors are usually located at the center of the wall, the windows at both sides of the door. For those walls without a door, the windows are located close to the corners. The window and door area is around 12% of the overall wall surface area. The average dimensions of doors are: width 1.00 m and height 2.10 m. The average dimensions of windows are: width 1.0 m and height 0.80 m.

2.3 Functional Planning

The main function of this building typology is single-family house. In rural areas, general use is residential. In urban areas, bahareque houses can also accommodate retail trade or handicraft businesses. In a typical building of this type, there are no elevators and no fire-protected exit staircases. Generally, these buildings have two doors, one at the front and one on the building's back side entering the backyard.

2.4 Modification to Building

In some cases, outer walls of bahareque buildings are supplemented by masonry walls added inside the structure (Figure 10). The most frequent modification of bahareque buildings is replacing the heavy day roof tiles with metal sheeting such as corrugated iron or aluminum plates.




Figure 5. Plan shape, cross-section and view of a typical residential bahareque building in a rural area (here: San Antonio Palop)




Figure 6. Plan shape, cross-sections and view of a typical bahareque building with an annex of adobe walls in a rural area (here: San Antonio Palop)




Figure 7. Plan shape, cross-section and view of a typical bahareque building with a wooden annex in a rural area (here: Soloma/Guatemala; taken from Marroquin and G)




Figure 8. Plan shape, cross-section and view of a typical bahareque building in a rural area (here: Purullh)




Figure 9. Plan shape, cross-section and view of a typical bahareque building in a rural area (here: Purullh)



Figure 10. Modification of a bahareque house by an additional wall at the inside made of masonry bricks (Santa Tecla).

3. Structural Details

3.1 Structural System

| Material | Type of Load-Bearing Structure | # | Subtypes | Most appropriate type |
|----------|--------------------------------|----|--|--------------------------|
| Masonry | Stone Masonry Walls | 1 | Rubble stone (field stone) in mud/lime mortar or without mortar (usually with timber roof) | <input type="checkbox"/> |
| | | 2 | Dressed stone masonry (in lime/cement mortar) | <input type="checkbox"/> |
| | Adobe/ Earthen Walls | 3 | Mud walls | <input type="checkbox"/> |
| | | 4 | Mud walls with horizontal wood elements | <input type="checkbox"/> |
| | | 5 | Adobe block walls | <input type="checkbox"/> |
| | | 6 | Rammed earth/Pise construction | <input type="checkbox"/> |
| | Unreinforced masonry walls | 7 | Brick masonry in mud/lime mortar | <input type="checkbox"/> |
| | | 8 | Brick masonry in mud/lime mortar with vertical posts | <input type="checkbox"/> |
| | | 9 | Brick masonry in lime/cement mortar | <input type="checkbox"/> |
| | | 10 | Concrete block masonry in cement mortar | <input type="checkbox"/> |
| | Confined masonry | 11 | Clay brick/tile masonry, with wooden posts and beams | <input type="checkbox"/> |
| | | 12 | Clay brick masonry, with concrete posts/tie columns and beams | <input type="checkbox"/> |
| | | 13 | Concrete blocks, tie columns and beams | <input type="checkbox"/> |
| | Reinforced masonry | 14 | Stone masonry in cement mortar | <input type="checkbox"/> |
| | | 15 | Clay brick masonry in cement mortar | <input type="checkbox"/> |
| | | 16 | Concrete block masonry in cement mortar | <input type="checkbox"/> |
| | Moment resisting frame | 17 | Flat slab structure | <input type="checkbox"/> |
| | | 18 | Designed for gravity loads only, with URM infill walls | <input type="checkbox"/> |
| | | 19 | Designed for seismic effects, with URM infill walls | <input type="checkbox"/> |
| | | 20 | Designed for seismic effects, with structural infill walls | <input type="checkbox"/> |

| | | | | | |
|---------------------|----------------------------|----|---|--|--------------------------|
| Structural concrete | Structural wall | 21 | Dual system – Frame with shear wall | <input type="checkbox"/> | |
| | | 22 | Moment frame with in-situ shear walls | <input type="checkbox"/> | |
| | | 23 | Moment frame with precast shear walls | <input type="checkbox"/> | |
| | Precast concrete | | 24 | Moment frame | <input type="checkbox"/> |
| | | | 25 | Prestressed moment frame with shear walls | <input type="checkbox"/> |
| | | | 26 | Large panel precast walls | <input type="checkbox"/> |
| | | | 27 | Shear wall structure with walls cast-in-situ | <input type="checkbox"/> |
| | | | 28 | Shear wall structure with precast wall panel structure | <input type="checkbox"/> |
| Steel | Moment-resisting frame | 29 | With brick masonry partitions | <input type="checkbox"/> | |
| | | 30 | With cast in-situ concrete walls | <input type="checkbox"/> | |
| | | 31 | With lightweight partitions | <input type="checkbox"/> | |
| | Braced frame | | 32 | Concentric connections in all panels | <input type="checkbox"/> |
| | | | 33 | Eccentric connections in a few panels | <input type="checkbox"/> |
| | Structural wall | | 34 | Bolted plate | <input type="checkbox"/> |
| | | | 35 | Welded plate | <input type="checkbox"/> |
| Timber | Load-bearing timber frame | 36 | Thatch | <input type="checkbox"/> | |
| | | 37 | Walls with bamboo/reed mesh and post (Wattle and Daub) | <input checked="" type="checkbox"/> | |
| | | 38 | Masonry with horizontal beams/planks at intermediate levels | <input type="checkbox"/> | |
| | | 39 | Post and beam frame (no special connections) | <input type="checkbox"/> | |
| | | 40 | Wood frame (with special connections) | <input type="checkbox"/> | |
| | | 41 | Stud-wall frame with plywood/gypsum board sheathing | <input type="checkbox"/> | |
| | | 42 | Wooden panel walls | <input type="checkbox"/> | |
| Other | Seismic protection systems | 43 | Building protected with base-isolation systems | <input type="checkbox"/> | |
| | | 44 | Building protected with seismic dampers | <input type="checkbox"/> | |
| | Hybrid systems | 45 | other (described below) | <input type="checkbox"/> | |

3.2 Gravity Load-Resisting System

The vertical load-resisting system is timber frame. Gravity loads from the roof construction itself (dead loads) or from live loads such as wind impact are directly transferred from the roof construction to the corner columns (wooden posts) which take the entire gravity load and transfer it to the ground (or foundation). In urban areas, most of the bahareque houses have a base (pedestal) forming the foundation made out of day bricks, field stones or even concrete. The base can reach up to one meter above the ground with the bahareque walls resting on it (Figure 14). The bahareque shacks found in rural areas often possess no foundation or only a strip footing comprised of field stones or bricks. Since the indigenous method of roof covering with palm fronds is mainly replaced by heavy day tiles or burnt adobe the largest gravity loads result from the weight roof construction.

3.3 Lateral Load-Resisting System

The lateral load-resisting system is timber frame. The lateral load-resisting system of bahareque houses principally consists of a flexible mixed wall construction made out of vertical timber elements and horizontal struts which are

fastened at regularly spaced intervals at the columns (Figure 11). Even though these wall constructions are packed with mud and day filler combined with chopped straws (or sometimes with whole canes), they show elasticity and are characterized by a very low self weight (Figure 12). In most cases, sufficient bracing of the walls, e.g. by diagonal trusses (Figure 13), is not provided resulting in a lack of adequate wall strength in both the in-plane and out-of-plane directions (Yoshimura and Kuroki, 2001). In addition, lateral resistance is reduced by the failure to set the vertical structural elements (wooden corner columns) deeply and firmly into the ground (Levin, 1940). The gabled roof generally consists of a light wood frame construction which is not able to support any lateral loading. At best, a tight connection of the roof construction with the walls can only be assumed at the corner columns.

3.4 Building Dimensions

The typical plan dimensions of these buildings are: lengths between 8 and 10 meters, and widths between 4 and 8 meters. The building has 0 to 1 storey(s). The typical span of the roofing/flooring system is 4-8 meters. Story heights vary between 1.8m and 3.0m. The typical storey height in such buildings is 2.4 meters. The typical structural wall density is up to 5%.

3.5 Floor and Roof System

| Material | Description of floor/roof system | Most appropriate floor | Most appropriate roof |
|---------------------|---|-------------------------------------|-------------------------------------|
| Masonry | Vaulted | <input type="checkbox"/> | <input type="checkbox"/> |
| | Composite system of concrete joists and masonry panels | <input type="checkbox"/> | <input type="checkbox"/> |
| Structural concrete | Solid slabs (cast-in-place) | <input type="checkbox"/> | <input type="checkbox"/> |
| | Waffle slabs (cast-in-place) | <input type="checkbox"/> | <input type="checkbox"/> |
| | Flat slabs (cast-in-place) | <input type="checkbox"/> | <input type="checkbox"/> |
| | Precast joist system | <input type="checkbox"/> | <input type="checkbox"/> |
| | Hollow core slab (precast) | <input type="checkbox"/> | <input type="checkbox"/> |
| | Solid slabs (precast) | <input type="checkbox"/> | <input type="checkbox"/> |
| | Beams and planks (precast) with concrete topping (cast-in-situ) | <input type="checkbox"/> | <input type="checkbox"/> |
| | Slabs (post-tensioned) | <input type="checkbox"/> | <input type="checkbox"/> |
| Steel | Composite steel deck with concrete slab (cast-in-situ) | <input type="checkbox"/> | <input type="checkbox"/> |
| Timber | Rammed earth with ballast and concrete or plaster finishing | <input type="checkbox"/> | <input type="checkbox"/> |
| | Wood planks or beams with ballast and concrete or plaster finishing | <input type="checkbox"/> | <input type="checkbox"/> |
| | Thatched roof supported on wood purlins | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| | Wood shingle roof | <input type="checkbox"/> | <input type="checkbox"/> |
| | Wood planks or beams that support clay tiles | <input type="checkbox"/> | <input type="checkbox"/> |
| | Wood planks or beams supporting natural stones slates | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| | Wood planks or beams that support slate, metal, asbestos-cement or plastic corrugated sheets or tiles | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| | Wood plank, plywood or manufactured wood panels on joists supported by beams or walls | <input type="checkbox"/> | <input type="checkbox"/> |
| Other | Described below | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |

The floor is made of earthen materials or cast plaster (screed). The roof is considered a flexible diaphragm. Details of a typical roof construction are given in Figure 15.

3.6 Foundation

| Type | Description | Most appropriate type |
|------|-------------|-----------------------|
| | | |

| | | |
|--------------------|--|-------------------------------------|
| Shallow foundation | Wall or column embedded in soil, without footing | <input type="checkbox"/> |
| | Rubble stone, fieldstone isolated footing | <input type="checkbox"/> |
| | Rubble stone, fieldstone strip footing | <input checked="" type="checkbox"/> |
| | Reinforced-concrete isolated footing | <input type="checkbox"/> |
| | Reinforced-concrete strip footing | <input checked="" type="checkbox"/> |
| | Mat foundation | <input type="checkbox"/> |
| | No foundation | <input checked="" type="checkbox"/> |
| Deep foundation | Reinforced-concrete bearing piles | <input type="checkbox"/> |
| | Reinforced-concrete skin friction piles | <input type="checkbox"/> |
| | Steel bearing piles | <input type="checkbox"/> |
| | Steel skin friction piles | <input type="checkbox"/> |
| | Wood piles | <input type="checkbox"/> |
| | Cast-in-place concrete piers | <input type="checkbox"/> |
| | Caissons | <input type="checkbox"/> |
| Other | Described below | <input type="checkbox"/> |

In rural areas, bahareque houses generally possess no foundation or only a strip footing of field stones or bricks. Here, the vertical timber elements are simply set firmly into the ground at the corners which in many reported cases is not sufficient. In urban areas, foundations are built as bases (pedestals) consisting of field stones, day bricks or concrete into which the vertical posts are inserted (Figure 14).



Figure 11. Detailing and fastening of the horizontal struts at the vertical timber elements. [Click to enlarge figures]




Figure 12. Detailing of a bahareque wall (after Carazas-Aedo and Rivero-Olmos, 2002)




Figure 13. Elevation view of a bahareque wall (after Carazas-Aedo and Rivero-Olmos, 2002).



Figure 14. Bahareque building in an urban area with a pedestal made of clay bricks.




Figure 15. Detailing of the wooden roof construction of bahareque houses (taken from Moisa-Perez and Medrano-Lizama, 1993).



Figure 16. Low adherence of plaster due to weathering effects and missing connection to the wall materials

4. Socio-Economic Aspects

4.1 Number of Housing Units and Inhabitants

Each building typically has 1 housing unit(s). Due to the small plan dimensions and thus small living area, generally only one family occupies these buildings. The number of inhabitants in a building during the day or business hours is less than 5. The number of inhabitants during the evening and night is 5-10.

4.2 Patterns of Occupancy

4.3 Economic Level of Inhabitants

| Income class | Most appropriate type |
|--------------------------------------|-------------------------------------|
| a) very low-income class (very poor) | <input checked="" type="checkbox"/> |
| b) low-income class (poor) | <input checked="" type="checkbox"/> |
| c) middle-income class | <input type="checkbox"/> |
| d) high-income class (rich) | <input type="checkbox"/> |

The housing unit price to annual income for very poor is US\$ 2000 / 4300, and for poor, it is US\$ 5000 / 7200.

| Ratio of housing unit price to annual income | Most appropriate type |
|--|-------------------------------------|
| 5:1 or worse | <input type="checkbox"/> |
| 4:1 | <input type="checkbox"/> |
| 3:1 | <input type="checkbox"/> |
| 1:1 or better | <input checked="" type="checkbox"/> |

| What is a typical source of financing for buildings of this type? | Most appropriate type |
|---|-------------------------------------|
| Owner financed | <input checked="" type="checkbox"/> |
| Personal savings | <input checked="" type="checkbox"/> |
| Informal network: friends and relatives | <input checked="" type="checkbox"/> |
| Small lending institutions / micro-finance institutions | <input type="checkbox"/> |
| Commercial banks/mortgages | <input type="checkbox"/> |
| Employers | <input type="checkbox"/> |
| Investment pools | <input type="checkbox"/> |
| Government-owned housing | <input type="checkbox"/> |
| Combination (explain below) | <input type="checkbox"/> |
| other (explain below) | <input type="checkbox"/> |

In each housing unit, there are 1 bathroom(s) without toilet(s), 1 toilet(s) only and no bathroom(s) including toilet(s).

However, in many cases (especially in rural areas), bahareque buildings have no internal latrines or bathrooms. The latrines are usually placed inside a small shack, which is located in the backyard. .

4.4 Ownership

The type of ownership or occupancy is outright ownership.

| Type of ownership or | Most appropriate type |
|----------------------|-----------------------|
|----------------------|-----------------------|

| | |
|---|-------------------------------------|
| occupancy? | |
| Renting | <input type="checkbox"/> |
| outright ownership | <input checked="" type="checkbox"/> |
| Ownership with debt (mortgage or other) | <input type="checkbox"/> |
| Individual ownership | <input type="checkbox"/> |
| Ownership by a group or pool of persons | <input type="checkbox"/> |
| Long-term lease | <input type="checkbox"/> |
| other (explain below) | <input type="checkbox"/> |

5. Seismic Vulnerability

5.1 Structural and Architectural Features

| Structural/ Architectural Feature | Statement | Most appropriate type | | |
|---|--|-------------------------------------|-------------------------------------|-------------------------------------|
| | | Yes | No | N/A |
| Lateral load path | The structure contains a complete load path for seismic force effects from any horizontal direction that serves to transfer inertial forces from the building to the foundation. | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Building Configuration | The building is regular with regards to both the plan and the elevation. | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Roof construction | The roof diaphragm is considered to be rigid and it is expected that the roof structure will maintain its integrity, i.e. shape and form, during an earthquake of intensity expected in this area. | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Floor construction | The floor diaphragm(s) are considered to be rigid and it is expected that the floor structure(s) will maintain its integrity during an earthquake of intensity expected in this area. | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| Foundation performance | There is no evidence of excessive foundation movement (e.g. settlement) that would affect the integrity or performance of the structure in an earthquake. | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Wall and frame structures-redundancy | The number of lines of walls or frames in each principal direction is greater than or equal to 2. | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Wall proportions | Height-to-thickness ratio of the shear walls at each floor level is: Less than 25 (concrete walls); Less than 30 (reinforced masonry walls); Less than 13 (unreinforced masonry walls); | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Foundation-wall connection | Vertical load-bearing elements (columns, walls) are attached to the foundations; concrete columns and walls are doweled into the foundation. | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Wall-roof connections | Exterior walls are anchored for out-of-plane seismic effects at each diaphragm level with metal anchors or straps | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Wall openings | The total width of door and window openings in a wall is: For brick masonry construction in cement mortar : less than 1/2 of the distance between the adjacent cross walls; For adobe masonry, stone masonry and brick masonry in mud mortar: less than 1/3 of the distance between the adjacent cross | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

| | | | | |
|-------------------------------|---|--------------------------|-------------------------------------|--------------------------|
| | walls; For precast concrete wall structures: less than 3/4 of the length of a perimeter wall. | | | |
| Quality of building materials | Quality of building materials is considered to be adequate per the requirements of national codes and standards (an estimate). | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Quality of workmanship | Quality of workmanship (based on visual inspection of few typical buildings) is considered to be good (per local construction standards). | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Maintenance | Buildings of this type are generally well maintained and there are no visible signs of deterioration of building elements (concrete, steel, timber) | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Additional Comments | | | | |

5.2 Seismic Features

| Structural Element | Seismic Deficiency | Earthquake Resilient Features | Earthquake Damage Patterns |
|-------------------------------|--|---|--|
| Wall | - insufficient bracing reducing wall strength - faulty tying of horizontal members to the columns reducing wall strength - deterioration of wall materials due to effects of climate and vermins | - flexibility, elasticity - low dead loads | - in-plane and out-of-plane failure |
| Frame (wooden corner columns) | - insufficient number of posts - insufficient foundation depth - lack of preservative treatment of timber leading to deterioration due to vermins (insects) - decay/rot of buried portion of column bases due to missing foundation and/or lack of preservative treatment | - flexibility, elasticity | - anchorage/embedding failure of wooden posts - diagonal shear cracking |
| Roof | - no diaphragm effect - no tight connection to the walls - high dead loads in case of heavy roof tiles (inverted pendulum) - material deterioration of wooden (or metal) trusses due to climatic effects | - low dead loads in case of palm fronds or corrugated iron sheeting | - total and partial collapse of roof construction |
| Other | - low adherence of plaster due to weathering effects and missing connection to the walls (Figure 16) | | - spalling of plaster |

5.3 Overall Seismic Vulnerability Rating

The overall rating of the seismic vulnerability of the housing type is C: MEDIUM VULNERABILITY (i.e., moderate seismic performance), the lower bound (i.e., the worst possible) is A: HIGH VULNERABILITY (i.e., very poor seismic performance), and the upper bound (i.e., the best possible) is D: MEDIUM-LOW VULNERABILITY (i.e., good seismic performance).

| | | | | | | |
|---------------------|-------------------------------------|--------------------------|--------------------------|-------------------------------------|--------------------------|--------------------------|
| Vulnerability | high | medium-high | medium | medium-low | low | very low |
| | very poor | poor | moderate | good | very good | excellent |
| Vulnerability Class | A | B | C | D | E | F |
| | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

5.4 History of Past Earthquakes

| Date | Epicenter, region | Magnitude | Max. Intensity |
|------|--|------------------------|--------------------|
| 1917 | June 8, West of San Salvador | Ms 6.7 | N.A. |
| 1919 | April 28, San Salvador | Ms 5.9 | N.A. |
| 1936 | Dec. 20, San Vicente | Ms 6.1 | VII-VIII (SIEBERG) |
| 1951 | May 6-7, Jucuapa, Chinameca, and Santiago de Maria | Ms 5.9, Ms 6.0, Ms 5.5 | I(MSK) < VIII |
| 1965 | May 3, San Salvador (d = 10 km) | Ms 5.9 | VIII (MMI) |
| 1982 | June 19, Pacific Ocean | Mw 7.3 | VII (MMI) |
| 1986 | Oct 10, South of San Salvador | Mw 5.7 (Ms 5.4) | VIII (MMI) |
| 2001 | Jan 13, Pacific Ocean (100 km southwest of San Miguel) | Mw 7.7 (Ms 7.8) | VII-VIII (MMI) |
| 2001 | Feb 13, San Juan Tepezontes | Mw 6.6 (Ms 6.5) | VII (MMI) |

The bahareque construction type is not covered by the vulnerability table of the European Macroseismic Scale EMS-1998 (Grünthal (ed.) et al., 1998). This building type has proven to perform better under lateral earthquake shaking than adobe structures. Additionally, its reported flexibility/elasticity as well as some favorable features such as the lightweight wall (and roof) construction may justify the classification into vulnerability class C. However, it should be stated, that this strongly depends on the quality of materials, workmanship, and the state of maintenance. Most of the bahareque buildings which can be found nowadays are older and show weathering effects and have to be classified into vulnerability class A.

1917: The use of bahareque construction techniques in the urban areas of San Salvador is forbidden by legislative decree, following the June 8 earthquake (Moisa-Perez and Medrano-Lizama, 1993).

1936, December 20 (local: December 19, 20:41 h) earthquake: According to Levin (1940), the intensity of the earthquake near the city San Vicente certainly exceeded grade VII of the Sieberg scale, and probably reached grade VIII. Uncertainties in the intensity assignment arise from the fact that most of the damage was concentrated on traditional building types, such as adobe or bahareque, which are not mentioned in the intensity scales, and due to the considerable number of buildings already damaged by foreshocks from the preceding morning. The isoseismal map of the earthquake was drawn largely with the following as a basis: Isoseismal zone VIII: poorly constructed or weak bahareque houses collapsed, plaster fell from the walls of well-constructed bahareque houses, some heavy tile roofs either collapsed or were considerably deformed. Isoseismal zone VII: good bahareque houses were unaffected except for falling plaster and deformation of tile roofs; some old or poorly constructed bahareque houses collapsed. Beyond isoseismal zone VI there was no visible damage to structures.

1951, May 6-7 (UTC: 23:03 h, 23:08 h on May 6 and 20:22 h on May 7): A series of three destructive earthquakes (Ms 5.9, Ms 6.0, Ms 5.5) destroyed the cities of Jucuapa and Chinameca with about 400 fatalities (Bommer et al., 2002) as well as the city of Santiago de Maria. The size of the affected area was very small, a few adobe and bahareque houses did withstand the shocks, but all of these had been built within two or three years prior to the earthquake? (Ambraseys et al., 2001).

1965, May 3 (UTC: 10:01 h): Rosenblueth and Prince (1966) report that at 4h 01 m 35s (local time) on the 3rd of May, 1965, the capital city of the Republic of El Salvador was shaken by an earthquake that caused severe damages and a death toll of 127 people (...). Its epicenter was located near the city in a distance of 10 km and a superficial focus of about 8 km. The Richter magnitude was computed as 6. Regarding the damages to bahareque buildings, the authors stated that the larger death toll was caused by the collapse of bahareque dwellings. However, the behavior of this type of constructions was satisfactory, generally; bahareque structures collapsed when three factors were present all together: the wood was rotten, the foundation soil was loose sand and it was located close by the area of maximum intensity.?

1986, October 10 (UTC: 17:49 h): Based on Harlow et al. (1993) the earthquake killed an estimated 1,500 people, injured 7,000 to 10,000 others, and left more than 100,000 people homeless (Olsen, 1987). The earthquake occurred on a shallow fault beneath the city of San Salvador at 11:49 a.m. local time and was assigned a surface-wave magnitude (Ms) of 5.4 by the U.S. National Earthquake Information Center. Whilst Anderson (1987) stated that new bahareque construction holds up well, on the average, under earthquake ground shaking. But failure of this building system during the earthquake, as well as failure of adobe construction, was extensive in the southern sector of San Salvador. This included the neighborhoods of Santa Anita, Modelo, and San Jacinto (near the Presidential Palace). Based on experiences in past Central American earthquakes, collapse of bahareque dwellings is often due to failure of the structural timber caused by rot or damage by insects. Figure 17 illustrates some damages to bahareque dwellings caused by the 1986 event.

2001, January 13 (17: 33 UTC) earthquake: The epicenter was located 100 km southwest of the city San Miguel in the subduction zone offshore from El Salvador. The depth of the mainshock was 39 km (NEIS). According to the Seismological Center of Central America (CASC) the maximum ground shaking intensity in the coastal area of El Salvador (near the epicenter) was $I(MMI) = VIII$, in most cities of El Salvador $I(MMI) = VII$ (Sawada et al., 2001; Yoshimura and Kuroki, 2001). Bommer et al. (2002) suggest that $I(MMI)$ intensities throughout the southern half of the country were between VI and VII with local pockets of higher intensity between VII and VIII. Examples of damaged bahareque houses within different villages of the region Usulután are given in Figure 18.

2001, February 13 (14:22 UTC) earthquake: It is reported that this event, with an epicenter close to the town of San Juan Tepezontes, caused maximum shaking intensities of VII-VIII (MMI) in the area from Lake Ilopango in the west to San Vicente in the east, and VI in San Salvador. However, a more recent study revealed that the maximum intensities did not exceed VII (Bommer et al., 2002). Figure 19 illustrates some damaged bahareque houses located in the city of San Vicente.

* based on information taken from: Ambraseys et al. (2001), Bommer et al. (2002), Lopez et al. (2004), Lopez et al. (2006), SNET (2004), Yoshimura and Kuroki (2001).



Figure 17. Damaged bahareque dwellings after the San Salvador earthquake on October 10, 1986 (left: San Jacinto neighborhood; right: after Kuroiwa, 1987). [Click to enlarge figures].



Figure 18. Structural damage to bahareque dwellings caused by the earthquake on January 13, 2001.



Figure 19. Structural damage to bahareque dwellings in the city of San Vicente caused by the earthquake on February 13, 2001.

6. Construction

6.1 Building Materials

| Structural element | Building material | Characteristic strength | Mix proportions/dimensions | Comments |
|--------------------------|--|--|---|----------|
| Walls | Building materials for the walls include timber slats, cane/reed, bamboo or wooden limbs with mud and clay filler. | There is no information on strengths of materials used in this construction. | Likewise, no information is available on the mix proportions of materials and on dimensions of walls. | |
| Foundation | The foundations are typically mud, fieldstones and concrete. | | | |
| Frames (beams & columns) | The frame (wooden corner columns) are made of (crudely) trimmed timber. | | | |
| Roof and floor(s) | The roofs are wooden bars with clay tiles or (corrugated) iron. The floors are of earthen materials or cast-in-place plaster (screed). | | | |

6.2 Builder

Generally, the building is occupied by the builder himself.

6.3 Construction Process, Problems and Phasing

Since this construction type is officially forbidden in San Salvador, information on the construction process is hard to obtain. The construction of this type of housing takes place in a single phase. Typically, the building is originally

designed for its final constructed size.

6.4 Design and Construction Expertise

During the design and construction no external expertise is involved. In most cases the builder erects the building for his own. Neither architects nor engineers are involved in the design or construction of these buildings.

6.5 Building Codes and Standards

This construction type is not addressed by the codes/standards of the country.

6.6 Building Permits and Development Control Rules

This type of construction is a non-engineered, and authorized as per development control rules.

This housing type is no longer built in urban areas. In rural areas, it is built without supervision by authorities. Building permits are not required to build this housing type.

6.7 Building Maintenance

Typically, the building of this housing type is maintained by Builder and Owner(s).

6.8 Construction Economics

This building typically cost US\$15 per square meter. This housing typically takes 75 man days to build.

7. Insurance

Earthquake insurance for this construction type is typically unavailable. For seismically strengthened existing buildings or new buildings incorporating seismically resilient features, an insurance premium discount or more complete coverage is unavailable.

8. Strengthening

8.1 Description of Seismic Strengthening Provisions

Strengthening of Existing Construction :

| Seismic Deficiency | Description of Seismic Strengthening provisions used |
|---|--|
| Heavy roof | Substitution of heavy roof tiles by (corrugated) iron sheeting |
| Weak roof construction | Tight connection to the walls; replace rotten wood elements |
| Deterioration of wooden elements due to climatic effects and vermin | Apply wood preservative (e.g. petrol) |
| Rotten column bases (wooden posts) | Apply wood preservative against moisture, vermins, and rodents (e.g. lime mortar) |
| Insufficient wall strength | Add (diagonal) bracing, additional horizontal struts (at the walls both inside and outside), additional tying of |

| | |
|---------------------|--|
| | horizontal members to the vertical posts, replace infill material with mud reinforced with organic fibers (e.g. hay) |
| Spalling of plaster | Use of lime-based plaster (also to protect the walls from humidity) and use of plaster reinforcement or lathing (e.g. barbed wire, wire netting) |

Strengthening of New Construction :

| Seismic Deficiency | Description of Seismic Strengthening provisions used |
|--|---|
| Heavy roof | Use of (corrugated) iron sheeting |
| Weak roof construction | Tight connections to the walls |
| Deterioration of wooden elements due to climate and vermin | Apply wood preservative (e.g. petrol) |
| Rotten column bases (wooden posts) | Rotten column bases (wooden posts) |
| Insufficient wall strength | Use of sawed lumber as vertical posts set firmly every 3 or 4 ft. into the ground (foundation) at the corners and at wall-panel points - Additional (diagonal) bracing - Additional or stronger horizontal struts of which the uppermost may serve as a beam at which the roof construction can be connected - Tying of horizontal members to the vertical posts |
| Spalling of plaster | Use of lime-based plaster (also to protect the walls from humidity) and use of plaster reinforcement or lathing (e.g. barbed wire, wire netting) |

A very detailed overview of strengthening and retrofitting measures for bahareque dwellings is given by Irula et al. (2002).

8.2 Seismic Strengthening Adopted

Has seismic strengthening described in the above table been performed in design and construction practice, and if so, to what extent?

Sporadically, seismic strengthening measures are applied especially to existing structures.

Was the work done as a mitigation effort on an undamaged building, or as repair following an earthquake?

No ongoing mitigation efforts on new or existing structures could be observed.

8.3 Construction and Performance of Seismic Strengthening

Reference(s)

1. The earthquake sequence of May 1951 at Jucuapa, El Salvador
Ambraseys, N.N., Bommer, J.J., Buforn, E., and Ud
Journal of Seismology, 2001, Vol.5, pp 23-39.
2. The El Salvador earthquakes of January and February 2001: Context, Characteristics and Implications for seismic risk
Bommer, J.J., Benito, M.B., Ciudad-Real, M., Lemoine, A., L
Soil Dynamics and Earthquake Engineering, 2002, Vol.22, pp 389
3. The San Salvador earthquake of October 10, 1986 - Review of building damage
Anderson, R.W.
Earthquake Spectra, EERI, 1987, Vol.3, pp 497-541.

4. Bahareque: Gu
Carazas-Aedo,W., and Rivero Olmos,A.
Ediciones CRATerre, MISEREOR, Francia, 27 pp, 2002.
5. Adobe housing in El Salvador: Earthquake performance and seismic improvement.
Dowling,D.M.
Special Paper 375: Natural Hazards in El Salvador, 2004, Vol.375 (0): pp 281
6. Preliminary Observations on the El Salvador Earthquakes of January 13 and February 13, 2001
EERI Special Earthquake Report
EERI, 2001, July.
7. Lecciones Aprendidas de los Terremotos del 2001 en El Salvador
Gobierno de El Salvador
Technical report, 112 pp, 2001.
8. European Macroseismic Scale 1998
(Eds.) Gr
Cahiers du Centre Europ 1998.
9. The San Salvador earthquake of 10 October 1986 and its Historical Context
Harlow ,D.H., White,R.A., Rymer,M.J., and Alvarado,S.
Bulletin of the Seismological Society of America, 1993, Vol.83 (4), pp 1143
10. Sistema de bahareque mejorado
Irula,H., Melhado,C., and H
Fundaci 2002.
11. Provisional Report on the January 13, 2001 Earthquake occurred off the Coast of El Salvador
Japan Society of Civil Engineers (JSCE)
Technical report, 14 pp, February 2001, 2001a.
12. The January 13, 2001 Off the Coast of El Salvador Earthquake. Investigation of Damage to Civil Engineering Structures, Buildings and Dwellings
Japan Society of Civil Engineers (JSCE)
Technical report, 112 pp, August 2001, 2001b.
13. El terremoto de San Salvador del 10 de octubre de 1986
Kuroiwa,J.
CISMID, Facultad de Ingenier 1987, Vol.01-87, 60 pp.
14. The Salvador Earthquakes of December, 1936
Levin, B.
Bulletin of the Seismological Society of America, 1940, Vol.27 (52), pp 377
15. The seismic performance of Bahareque dwellings in El Salvador
L
Proc. of the 13th World Conference on Earthquake Engineering, Vancouver, BC, Canada, 2004, Paper No. 2646.
16. Adobe Houses in El Salvador
L
EERI and IAEE World Housing Encyclopedia, 2006, Housing Report No.14.
17. La vivienda popular en Guatemala - Antes y despues del terremoto de 1976
Marroquin,H., and G
Tomo I, Universitaria de Guatemala, 1976.
18. Manual de construcci
Minke,G.
Technical report, Forschungslabor f 2001, 51 pp.
19. The San Salvador Earthquake of October 10, 1986
Olsen,R.A.
Earthquake Spectra, EERI, 1987, Vol.3, pp 415

20. Sistemas constructivos tradicionales en la arquitectura de El Salvador
Moisa-Perez,L.C., and Medrano-Lizama,C.C.
Tesis, San Salvador, 166 pp, 1993.
21. El temblor de San Salvador, 3 de mayo 1965
Rosenblueth,E., and Prince,J.
Ingenier 1966.
22. Preliminary report on damage caused by the El Salvador earthquake of January 13, 2001
Sawada,S., Katsuma,H, Yamasaki,Y., and Seo,K.
Japan Earthquake Engineering NEWS (in Japanese), 2001, Vol.177, pp 20
23. Sismos en El Salvador 1900-2001: Contexto
SNET
Technical report, 14 pp., April, 2004.
24. Damage to masonry buildings caused by the El Salvador earthquake of January 13, 2001
Yoshimura,K., and Kuroki,M.
Journal of Natural Disaster Science, 2001, Vol.23(2), pp 53

Author(s)

1. Dominik Lang
Dr./Researcher, NORSAR
Instituttveien 25, Postboks 53, Kjeller 2027, NORWAY
Email:dominik@norsar.no FAX: +47-63818719
2. Roberto Merlos
M.Sc., Universidad Centroamericana Jos
Boulevard Los Proceres,, San Salvador , EL SALVADOR
Email:rmerlos@ing.uca.edu.sv FAX: +503-22106662
3. Lisa Holliday
Engineer, Fears Laboratory, The University of Oklahoma, Norman, Oklahoma 73019, USA
Email:lisaholliday@ou.edu
4. Manuel A. Lopez M.
Engineer, Escuela de Ingenier, Universidad de El Salvador
Final 25 Av. Norte, San Salvador , EL SALVADOR
Email:manuel.lopez@unipv.it FAX: 503-225-2506

Reviewer(s)

1. Qaisar Ali
Associate Professor
Department of Civil Engineering, NWFP University of Engineering and Technology Pesh
Peshawar 25000, PAKISTAN
Email:engrqaisarali@yahoo.com FAX: -9217977

Save page as

