## World Housing Encyclopedia

an Encyclopedia of Housing Construction in Seismically Active Areas of the World



an initiative of Earthquake Engineering Research Institute (EERI) and International Association for Earthquake Engineering (IAEE)

# HOUSING REPORT Stone masonry apartment building

Report #	75
Report Date	05-06-2002
Country	ALGERIA
Housing Type	Stone Masonry House
Housing Sub-Type	Stone Masonry House : Rubble stone without/with mud/lime/cement mortar
Author(s)	Mohammed Farsi, Farah Lazzali, Yamina Ait-M
Reviewer(s)	Marjana Lutman

#### Important

This encyclopedia contains information contributed by various earthquake engineering professionals around the world. All opinions, findings, conclusions & recommendations expressed herein are those of the various participants, and do not necessarily reflect the views of the Earthquake Engineering Research Institute, the International Association for Earthquake Engineering, the Engineering Information Foundation, John A. Martin & Associates, Inc. or the participants' organizations.

#### Summary

This is a typical residential construction type found in most Algerian urban centers, constituting 40 to 50% of the total urban housing stock. This construction, built mostly before the 1950s by French contractors, is no longer practiced. Buildings of this type are typically 4 to 6 stories high. The slabs are wooden structures or shallow arches supported by steel beams (jack arch system). Stone masonry walls, usually 400 to 600 mm thick, have adequate gravity load-bearing capacity; however, their lateral load resistance is very low. As a result, these buildings are considered to be highly vulnerable to seismic effects.

## 1. General Information

Buildings of this construction type can be found in northern Algeria. In particular, the multi-story buildings exist mainly in the major cities, e.g. Algiers, Oran, Constantine, Annaba, etc. This construction type may constitute 40 to 50% of the urban housing stock. This type of housing construction is commonly found in urban areas.

This type of construction is found in the older urban districts.

This construction type has been in practice for less than 200 years.

Currently, this type of construction is not being built. This construction was practiced prior to 1950 by French contractors.




Figure 1: Typical Building

Figure 1B: A typical old stone masonry building in Figure 2: Perspective Drawing Showing Key Load-Algiers city Bearing Elements

## 2. Architectural Aspects

#### 2.1 Siting

These buildings are typically found in flat, sloped and hilly terrain. They do not share common walls with adjacent buildings. When separated from adjacent buildings, the typical distance from a neighboring building is 5 meters.

### 2.2 Building Configuration

The building plan for this housing type can be of different forms: rectangular, L-shaped, U-shaped, etc. The number, size and position of openings for a typical floor in a building are shown on the typical plan (Figure 3A). The total window and door area is about 25% of the overall wall surface area.

### 2.3 Functional Planning

The main function of this building typology is mixed use (both commercial and residential use). Buildings of this type are also used as offices and hospitals. In a typical building of this type, there are no elevators and 1-2 fire-protected exit staircases. The majority of these multi-storied buildings have only one exit and one main interior staircase.

### 2.4 Modification to Building

Modifications are often undertaken by the residents without any professional assistance provided by engineers. The modifications include the demolition of interior walls, opening commercial areas, and vertical extensions.




Figure 3B: Typical Roof Plan

## 3. Structural Details

## 3.1 Structural System

Material	Type of Load-Bearing Struct	ture #	Subtypes	Most appropriate type
	Stone Masonry Walls	1	Rubble stone (field stone) in mud/lime mortar or without mortar (usually with timber roof)	
	wans	2	Dressed stone masonry (in lime/cement mortar)	
		3	Mud walls	
	Adobe/ Earthen Walls	4	Mud walls with horizontal wood elements	
	Adobe/ Earthen wans	5	Adobe block walls	
		6	Rammed earth/Pise construction	
		7	Brick masonry in mud/lime mortar	
	Unreinforced masonry	8	Brick masonry in mud/lime mortar with vertical posts	
Masonry	walls	9	Brick masonry in lime/cement mortar	
		10	Concrete block masonry in cement mortar	
		1	Clay brick/tile masonry, with wooden posts and beams	
	Confined masonry	12	Clay brick masonry, with 2 concrete posts/tie columns and beams	
		1.	Concrete blocks, tie columns and beams	
		14	Stone masonry in cement mortar	
	Reinforced masonry	15	Clay brick masonry in cement mortar	
		10	Concrete block masonry in cement mortar	
		1	Flat slab structure	
		ľ		

		18	Designed for gravity loads only, with URM infill walls	
	Moment resisting frame	19	Designed for seismic effects, with URM infill walls	
		20	Designed for seismic effects, with structural infill walls	
		21	Dual system – Frame with shear wall	
	Structural wall	22	Moment frame with in-situ shear walls	
Structural concrete		23	Moment frame with precast shear walls	
		24	Moment frame	
		25	Prestressed moment frame with shear walls	
	Precast concrete	26	Large panel precast walls	
		27	Shear wall structure with walls cast-in-situ	
		28	Shear wall structure with precast wall panel structure	
		29		
	Moment-resisting frame	30	With cast in-situ concrete walls	
		31	With lightweight partitions	
Steel	Braced frame	32	Concentric connections in all panels	
		33	Eccentric connections in a few panels	
	Structural wall		Bolted plate	
		==	Welded plate	
		36	Thatch	
	Load-bearing timber frame	37	Walls with bamboo/reed mesh and post (Wattle and Daub)	
		38	Masonry with horizontal beams/planks at intermediate levels	
Timber		39	Post and beam frame (no special connections)	
		40	Wood frame (with special connections)	
		41	Stud-wall frame with plywood/gypsum board sheathing	
		==	Wooden panel walls	
	Seismic protection systems	43	Building protected with base-isolation systems	
Other			Building protected with seismic dampers	
	Hybrid systems	45	other (described below)	

### 3.2 Gravity Load-Resisting System

The vertical load-resisting system is stone masonry walls. Stone masonry walls are the principal elements of the gravity load-bearing structure.

### 3.3 Lateral Load-Resisting System

The lateral load-resisting system is stone masonry walls. The lateral load-resisting system consists of the stone masonry walls built in longitudinal and cross directions. Wall thickness varies from 400 to 600 mm. Field masonry has been mainly used, and massive stones exist only at the corners and around the openings. Low-strength mortar (either cement and/or mud mortar) has been used. According to the Algerian Seismic Code (RPA99) and the Strengthening Guide, many buildings of this structural type have been strengthened after suffering damages during the last earthquakes (El

Asnam 1980, Tipaza 1989, Mascar 1994 and Ain Temouchent 1999). They were strengthened with reinforced concrete ties in both vertical and horizontal directions and with RC slabs used as floor and roof structures. The maximum building height allowed by the Code depends on the seismic zone (17 m, 14 m and 11 m, for seismic zones I, II and III, respectively).

#### 3.4 Building Dimensions

The typical plan dimensions of these buildings are: lengths between 25 and 25 meters, and widths between 15 and 15 meters. The building is 5 storey high. The typical span of the roofing/flooring system is 4 meters. The typical storey height in such buildings is 3.5 meters. The typical structural wall density is up to 5 %. 5% - 6% The ratio of the total wall area/plan area (for each floor) in each principal direction is between 5% and 6%.

### 3.5 Floor and Roof System

Material	Description of floor/roof system	Most appropriate floor	Most appropriate roof
	Vaulted		
Masonry	Composite system of concrete joists and masonry panels		
	Solid slabs (cast-in-place)		
	Waffle slabs (cast-in-place)		
	Flat slabs (cast-in-place)		
	Precast joist system		
Structural concrete	Hollow core slab (precast)		
	Solid slabs (precast)		
	Beams and planks (precast) with concrete topping (cast-in-situ)		
	Slabs (post-tensioned)		
Steel	Composite steel deck with concrete slab (cast-in-situ)		
	Rammed earth with ballast and concrete or plaster finishing		
	Wood planks or beams with ballast and concrete or plaster finishing		
	Thatched roof supported on wood purlins		
	Wood shingle roof		
Timber	Wood planks or beams that support clay tiles		
	Wood planks or beams supporting natural stones slates		
	Wood planks or beams that support slate, metal, asbestos-cement or plastic corrugated sheets or tiles		
	Wood plank, plywood or manufactured wood panels on joists supported by beams or walls		
Other	Described below		

Masonry and steel jack arch structure. Floor and roof structures are not considered as rigid diaphragms.

## 3.6 Foundation

Туре	Description	Most appropriate type
	Wall or column embedded in soil, without footing	
	Rubble stone, fieldstone isolated footing	
Shallow foundation	Rubble stone, fieldstone strip footing	
	Reinforced-concrete isolated footing	
	Reinforced-concrete strip	

	footing	
	Mat foundation	
	No foundation	
	Reinforced-concrete bearing piles	
	Reinforced-concrete skin friction piles	
	Steel bearing piles	
Deep foundation	Steel skin friction piles	
	Wood piles	
	Cast-in-place concrete piers	
	Caissons	
Other	Described below	




Figure 4: Critical Structural Details: Wall-Roof Connection and Vaulted Brick Floor Structure

## 4. Socio-Economic Aspects

#### 4.1 Number of Housing Units and Inhabitants

Each building typically has 10-20 housing unit(s). 10-15 units in each building. The number of inhabitants in a building during the day or business hours is 11-20. The number of inhabitants during the evening and night is more than 20. In most cases the women in the families are not working outside the home and are at home during the day.

#### 4.2 Patterns of Occupancy

There is a serious housing crisis in Algeria. On average, two generations occupy the same housing unit: parents and the family unit of an adult child.

#### 4.3 Economic Level of Inhabitants

Income class	Most appropriate type
a) very low-income class (very poor)	
b) low-income class (poor)	
c) middle-income class	
d) high-income class (rich)	

Economic Level: For the Poor Class the ratio of Housing Price Unit to their Annual Income is 10:1.

Ratio of housing unit price to annual incom	ne Most appropriate type
5:1 or worse	
4:1	
3:1	
1:1 or better	

What is a typical source of financing for buildings of this type?	Most appropriate type
Owner financed	
Personal savings	
Informal network: friends and relatives	
Small lending institutions / micro- finance institutions	
Commercial banks/mortgages	
Employers	
Investment pools	
Government-owned housing	
Combination (explain below)	
other (explain below)	

In each housing unit, there are 1 bathroom(s) without toilet(s), 1 toilet(s) only and 1 bathroom(s) including toilet(s).

### 4.4 Ownership

The type of ownership or occupancy is renting and outright ownership.

Type of ownership or occupancy?	Most appropriate type
Renting	
outright ownership	
Ownership with debt (mortgage or other)	
Individual ownership	
Ownership by a group or pool of persons	
Long-term lease	
other (explain below)	

## 5. Seismic Vulnerability

Structural/		Most appropriate type			
Architectural Feature	Statement	True	False	N/A	
Lateral load path	The structure contains a complete load path for seismic force effects from any horizontal direction that serves to transfer inertial forces from the building to the foundation.				
Building Configuration	The building is regular with regards to both the plan and the elevation.				
Roof construction	The roof diaphragm is considered to be rigid and it is expected that the roof structure will maintain its integrity, i.e. shape and form, during an earthquake of intensity expected in this area.				
Floor construction	The floor diaphragm(s) are considered to be rigid and it is expected that the floor structure(s) will maintain its integrity during an earthquake of intensity expected in this area.				
Foundation performance	There is no evidence of excessive foundation movement (e.g. settlement) that would affect the integrity or performance of the structure in an earthquake.				
Wall and frame structures- redundancy	The number of lines of walls or frames in each principal direction is greater than or equal to 2.				
Wall proportions	Height-to-thickness ratio of the shear walls at each floor level is: Less than 25 (concrete walls); Less than 30 (reinforced masonry walls);				
Foundation-wall connection	Less than 13 (unreinforced masonry walls); Vertical load-bearing elements (columns, walls) are attached to the foundations; concrete columns and walls are doweled into the foundation.				
Wall-roof connections	Exterior walls are anchored for out-of-plane seismic effects at each diaphragm level with metal anchors or straps				
Wall openings	The total width of door and window openings in a wall is: For brick masonry construction in cement mortar : less than ½ of the distance between the adjacent cross walls; For adobe masonry, stone masonry and brick masonry in mud mortar: less than 1/3 of the distance between the adjacent cross walls; For precast concrete wall structures: less than 3/4 of the length of a perimeter wall.				
Quality of building materials	Quality of building materials is considered to be adequate per the requirements of national codes and standards (an estimate).				
Quality of workmanship	Quality of workmanship (based on visual inspection of few typical buildings) is considered to be good (per local construction standards).				
Maintenance	Buildings of this type are generally well maintained and there are no visible signs of deterioration of building elements (concrete, steel, timber)				
Other					

## 5.1 Structural and Architectural Features

## **5.2 Seismic Features**

Structural Element	Seismic Deficiency	Earthquake Resilient Features	Earthquake Damage Patterns
Wall	Poor mortar strength; walls not tied		X-cracks and total collapse in some cases; very low seismic
	together		resistance

Frame (columns, beams)		
Roof and floors	Not monolithic; not rigid in-plane	
Other		

### 5.3 Overall Seismic Vulnerability Rating

The overall rating of the seismic vulnerability of the housing type is A: HIGH VULNERABILITY (i.e., very poor seismic performance), the lower bound (i.e., the worst possible) is A: HIGH VULNERABILITY (i.e., very poor seismic performance), and the upper bound (i.e., the best possible) is A: HIGH VULNERABILITY (i.e., very poor seismic performance).

Vulnerability	high	medium-high	medium	medium-low	low	very low
	very poor	poor	moderate	good	very good	excellent
Vulnerability	А	В	С	D	Е	F
Class						

## 5.4 History of Past Earthquakes

Date	Epicenter, region	Magnitude	Max. Intensity
1980	El-Asnam	7.3	X (MMI)
1989	Tipaza	6.2	VIII-IX (MSK)
1994	Mascara	5.6	VIII (MSK)
1999	Ain-Témouchent	5.8	VIII (MSK)

Buildings of this type were affected by the May 21, 2003 earthquake with the epicenter close to Zemmouri. The earthquake was of magnitude Mw= 6.8 and the intensity was IX-X (MMI scale). In general damage patterns vary from diagonal "X"-cracks to total wall collapse, and partial to total collapse of the roofs/slabs. Earthquake, Total Number of Apartment Buildings (all types), Damage level (MSK scale) 1 2 3 4 5 1980 El-Asnam, 4844 439 1304 1351 863 887 1989 Tipaza, 4511 1480 1102 223 426 1280 1994 Mascara, 1874 470 302 351 212 539 1999 Ain-Témouchent, 3398 1062 606 684 528 518.







Figure 5A: Typical Earthquake Damage: Partial Roof Collapse (1999 Ain-Temouchent Earthquake)

Figure 5B: Typical Earthquake Damage: Collapsed Roof of a Masonry Building (1989 Tipaza Earthquake)

Figure 5C: Typical Earthquake Damage: Cracking in the Wall Corners







- Figure 5F: Totally collapsed stone masonry building in Dellys (Boumerdes) in the May 21, 2003 earthquake
- Figure 5D: Damage to a stone masonry building in multi-storey stone masonry building in Algiers city Algiers in the May 21, 2003 earthquake



Figure 5E: Collapse of a roof and a side wall na in the May 21, 2003 earthquake



Figure 5G: Collapse of the vaulted brick and steel<br/>floor system in the May 21, 2003 earthquake (EI<br/>Harrach district, Algiers)Figure 5I: Collapse of a rubble stone masonry wall<br/>made of river stones and mud mortar in the May<br/>21, 2003 earthquake (Sidi Daoud, Boumerdes)

## 6. Construction

#### 6.1 Building Materials

Structural element	Building material	( 'baracteristic strength	Mix proportions/dimensions	Comments
Walls		Massive stones used at the corners and around the openings		Data not available
Foundation	Field stone in cement or mud mortar			
Frames (beams & columns)				
Roof and floor(s)	Vaulted bricks			

#### 6.2 Builder

This construction was practiced prior to 1950 by French contractors.

#### 6.3 Construction Process, Problems and Phasing

Owners and contractors were involved in the construction of this type. The stone blocks were laid by hand and basic construction equipment was used. (See Figures 7a--7h.). The construction of this type of housing takes place incrementally over time. Typically, the building is originally not designed for its final constructed size.

#### 6.4 Design and Construction Expertise

The level of expertise of all parties involved in the design and construction process was at the 20th century level worldwide. Only architects had a role in the design/construction of this housing type.

#### 6.5 Building Codes and Standards

This construction type is not addressed by the codes/standards of the country.

Not applicable - building codes are not applicable to this construction practice.

#### 6.6 Building Permits and Development Control Rules

This type of construction is a non-engineered, and not authorized as per development control rules.

Permits are now required for public buildings for the vertical extensions, structural interventions and for repair and strengthening. Building permits are not required to build this housing type.

#### 6.7 Building Maintenance

Typically, the building of this housing type is maintained by Owner(s) and Tenant(s).

#### **6.8 Construction Economics**

10,000-15,000 Algerian Dinars /m² (150-200 \$US/m²). Information not available.

## 7. Insurance

Earthquake insurance for this construction type is typically unavailable. For seismically strengthened existing buildings or new buildings incorporating seismically resilient features, an insurance premium discount or more complete coverage is unavailable.

## 8. Strengthening

#### 8.1 Description of Seismic Strengthening Provisions

Seismic Deficiency	Description of Seismic Strengthening provisions used	
Cracks in the stone masonry walls	RC jacketing	
Lack of integrity	Installation of horizontal and vertical RC ties at exterior and steel ties in the interior (see Figure 6A).	

#### Strengthening of Existing Construction :

#### 8.2 Seismic Strengthening Adopted

Has seismic strengthening described in the above table been performed in design and construction practice, and if so, to what extent?

These strengthening techniques were used to repair and strengthen the damaged buildings after the Algerian earthquakes reported in this contribution. A guide for using these seismic strengthening techniques is available in Algeria ("Méthodes de Réparation et de Renforcement des Ouvrages", was edited by CGS in 1992).

Was the work done as a mitigation effort on an undamaged building, or as repair following an earthquake? Vulnerability studies for strategic buildings were done in 1996 at Algiers City, and some buildings of this type were strengthened as a result of the study.


### 8.3 Construction and Performance of Seismic Strengthening

Was the construction inspected in the same manner as the new construction? No.

Who performed the construction seismic retrofit measures: a contractor, or owner/user? Was an architect or engineer involved?

A contractor performed the construction, and engineers were involved.

What was the performance of retrofitted buildings of this type in subsequent earthquakes? Good.










Figure 6A: Seismic Strengthening Techniques: Provision of Horizontal and Vertical RC Ties at the Exterior and Horizontal Steel Ties at the Interior

Figure 6B: Seismic Strengthening Techniques: An Example of a Strengthened Building with Vertical and Horizontal RC Ties at the First Floor Level

Figure 6C: Seismic Strengthening Techniques: Construction of RC Ties



Figure 8: Young victims of 21 May 2003 earthquake in AI Bordj Menail city- there is a hope in spite of the tragedy that affected population and caused severe human and economic losses; the earthquake killed more than 2,200 people, injured more

## Reference(s)

- 1. Seismic Vulnerability and Risk Evaluation for Old Urban Nuclei Benedetti, D., Benzoni, G., and Parisi, M.A. Earthquake Engineering and Structural Dynamics, Vol. 16, 183-201 1988
- 2. Auscultation de B Boutin,C., Ibraim,E. and Hans,S. V 1999
- Pour une approche exp Boutin,C., Hans,S. and Ibraim,E. Revue fran 2000 3.
- 4. Factors Determining Casuality Levels in Earthquakes: Mortality Prediction in Building Collapse Coburn, A.W., Spence, R.J.S., and Pomonis, A. 10th WCEE, Madrid, Spain 1992
- 5. R Centre National de Recherche Appliqu 2000
- Assessment of Earthquake Vulnerability of Buildings 6.

Cochrane,S.W., and Schaad,W.H. 10 WCEE, Madrid, Spain 2000

- 7. European Macroseismic Scale 1992 Ed. Gr European Seismological Commission, Luxembourg 1992
- The Mont Chenoua (Algeria) earthquake of October 29th, 1989: Damage assessment and distribution Farsi,M.N., and Belazougui,M. 10WCEE, Madrid, Spain. 1992
- 9. Identification des Structures de G Farsi,M.N. Th 1996
- Vulnerability and the MSK Scale Karnik,V., Schenkova,Z., and Schenk,V. Engineering Geology, 20, 161-168 1984

## Author(s)

- Mohammed Farsi Head of Department, CGS Kaddour Rahim Street BP 252, Algiers 16040, ALGERIA Email:mnfarsi@cgs-dz.org FAX: (213) 21 49 55 36
- Farah Lazzali Researcher, Dept. genie civil, FSI, Universite de Boumerdes, Boumerdes 35000, ALGERIA Email:lazzalifarah@umbb.dz FAX: (213) 21 49 55 36
- Yamina Ait-M Researcher, CGS Kaddour Rahim Street BP 252, Algiers 16040, ALGERIA FAX: (213) 21 49 55 36

## Reviewer(s)

 Marjana Lutman Research Engineer

 Slovenian National Building & Civil Engineering In Ljubljana 1000, SLOVENIA Email:marjana.lutman@zag.si FAX: (386) 1 2804 484



