GEM Building Taxonomy Report

-CIP/LFM+DUC/YEX:2002/HEX:10+HBEX:0+HFEX:3.1+HD:0/RES+RES2B/BP1/PLFR/IRRE/EWMA/RSH1+RM⁻

Juan Carlos Vielma Pérez



Taxonomy string:

DX /CR+CIP /LFM+DUC /DY /CR+CIP /LFM+DUC /YEX:2002 /HEX:10+HBEX:0+HFEX:3.1+HD:0 /RES+RES2B /BP1 /PLFR /IRRE /EWMA /RSH1+RMT1+RC+RC2+RTDN /FC+FC2 /FOSSL Material type (direction 1): Material technology (direction 1): Concrete, reinforced Cast-in-place concrete Material properties (direction 1): Material techonology (additional, direction 1): System ductility (direction 1): Ductile Lateral load-resisting system (direction 1): Moment frame Material technology (direction 2): Material type (direction 2): Concrete, reinforced Cast-in-place concrete Material properties (direction 2): Material techonology (additional, direction 2): Lateral load-resisting system (direction 2): System ductility (direction 2): **D**uctile Moment frame Foundations: Plan shape: Shallow foundation, with lateral capacity Rectangular, solid Type of Irregularity: Building position within a block: One adjacent building Regular structure Plan structural irregularity - primary: Vertical structural irregularity - primary: Plan structural irregularity - secondary: Vertical structural irregularity - secondary: Roof shape: Roof covering: Flat Clay or concrete tile Roof system material: Roof system type: Cast-in-place beam-supported RC roof Concrete Roof connections: Roof tie-down not provided Floor system material: Floor system type: Cast-in-place beam-supported RC floor Concrete Floor connections: Floor-wall diaphragm connection, unknown Exterior walls material: Masonry Date of constrution: 2002 Exact date of construction or retrofit Number of storeys above the ground: Number of storeys below the ground: 10 Exact number of storeys Exact number of storeys 0 Height of the grade above ground floor: Slope of the ground (for buildings on slopes): Exact height above grade 3.1 Slope of the ground 0 Occupancy type - detail: Occupancy type - general: Residential 3-4 Units Country: Region (province, state, etc.): Venezuela l ara Summary:

This is a typical residential building as we have in urab areas of Venezuela. Its typology is moment resisting frames in both orthogonal directions designed for high ductility response. The seismic hazard for our city is high, with a basic acceleration of 0.3g.