## **GEM Building Taxonomy Report**

Scawthorn Japan - 10

Scawthorn



Taxonomy string:

DX /S+SR+BOL /LFBR+DNO /DY /S+SR /LFBR+DNO /YAPP:1960 /HEX:2+HBEX:0+HFEX:0+HD:0 /IND+IND2 /BPD /PLFR /IRRE /EWSL /RSH2+RMT2+RME+RME1 / /FOSN

1960

2

0

Material type (direction 1): Steel Material properties (direction 1): **Bolted connections** Lateral load-resisting system (direction 1): Braced frame Material type (direction 2): Steel Material properties (direction 2): Welded connections Lateral load-resisting system (direction 2): Braced frame Foundations: Shallow foundation, with no lateral capacity Type of Irregularity: **Regular structure** Plan structural irregularity - primary: Plan structural irregularity - secondary: Roof shape: Pitched with gable ends Roof system material: Metal Roof connections: Roof-wall diaphragm connection unknown Floor system material: Floor material, unknown Floor connections: Floor-wall diaphragm connection, unknown Material technology (direction 1): Hot-rolled steel members Material technology (additional, direction 1):

System ductility (direction 1): Non-ductile Material technology (direction 2):

Hot-rolled steel members

Material techonology (additional, direction 2):

System ductility (direction 2): Non-ductile

Plan shape: Rectangular, solid

Building position within a block: Detached building

Vertical structural irregularity - primary:

Vertical structural irregularity - secondary:

Roof covering: Fibre cement or metal tile

Roof system type: Metal beams or trusses supporting light roofing

Floor system type:

Exterior walls material:

Stucco finish on light framing

Date of constrution:

Approximate date of construction or retrofit
Number of storeys above the ground:
Exact number of storeys
Height of the grade above ground floor: Exact height above grade
Occupancy type - general: Industrial
Country: Japan
Summary:

Rod bracing indicates metal framing.

