## **GEM Building Taxonomy Report**

## Testing Attributes for a Building located in Karachi, Pakistan Najia Siddiqui

## Picture not available

Taxonomy string: DX /CR+CIP /LFM /DY /CR+CIP /LFM / /HEX:5+HBEX:1+HFBET:10',15' /EDU+EDU3 / /PLFR /IRRE /EWMA /RSH1+RMN+RC /FO /FOSO

Material type (direction 1): Concrete, reinforced Cast-in-place concrete Material properties (direction 1): Lateral load-resisting system (direction 1): Ductility unknown Moment frame Material type (direction 2): Cast-in-place concrete Concrete, reinforced Material properties (direction 2): Lateral load-resisting system (direction 2): Ductility unknown Moment frame Foundations: Plan shape: Foundation, other Rectangular, solid Type of Irregularity: Regular structure Plan structural irregularity - primary: Plan structural irregularity - secondary: Roof shape: Roof covering: Flat Roof system material: Roof system type: Concrete, unknown Concrete Roof connections: Roof-wall diaphragm connection unknown Floor system material: Floor system type: Floor material, other Floor connections: Floor-wall diaphragm connection, unknown Exterior walls material: Masonry Date of constrution: Year unknown Number of storeys above the ground: 5 Exact number of storeys Height of the grade above ground floor: Range of height above grade 10'-15' Unknown slope Occupancy type - general: Education Country: Pakistan Karachi Summary:

Material technology (direction 1): Material techonology (additional, direction 1):

System ductility (direction 1): Material technology (direction 2): Material techonology (additional, direction 2):

System ductility (direction 2):

Building position within a block: Unknown building position

Vertical structural irregularity - primary:

Vertical structural irregularity - secondary:

Concrete roof, no covering

Number of storeys below the ground: Exact number of storeys 1 Slope of the ground (for buildings on slopes): Occupancy type - detail: College/university, offices and/or classrooms Region (province, state, etc.):