

# GEM Building Taxonomy Report

RC infilled frame building housing two departments of the Civil Engineering Faculty  
Demeter I.



## Taxonomy string:

DX+PF /CR+CIP /LFINF /DY+OF /CR+CIP /LFINF /YAPP:1975 /HEX:3+HBEX:0+HFAPP:0.3+HD:0 /EDU+EDU3 /BP1 /PLFR /IRIR+IRPP:TOR+IRVP:SET  
/EWMA /RSH3+RMT6+RWO+RWO1 /FC+FC2 /

## Material type (direction 1):

Concrete, reinforced

## Material properties (direction 1):

## Lateral load-resisting system (direction 1):

Infilled frame

## Material type (direction 2):

Concrete, reinforced

## Material properties (direction 2):

## Lateral load-resisting system (direction 2):

Infilled frame

## Foundations:

Unknown foundation system

## Type of Irregularity:

Irregular structure

## Plan structural irregularity - primary:

Torsion eccentricity

## Plan structural irregularity - secondary:

Setback

## Roof shape:

Pitched and hipped

## Roof system material:

Wood

## Roof connections:

Roof-wall diaphragm connection unknown

## Floor system material:

Concrete

## Floor connections:

Floor-wall diaphragm connection, unknown

## Exterior walls material:

Masonry

## Date of construction:

Approximate date of construction or retrofit 1975

## Number of storeys above the ground:

Exact number of storeys 3

## Height of the grade above ground floor:

Approximate height above grade 0.3

## Occupancy type - general:

Education

## Country:

Romania

## Summary:

## Material technology (direction 1):

Cast-in-place concrete

## Material technology (additional, direction 1):

## System ductility (direction 1):

Ductility unknown

## Material technology (direction 2):

Cast-in-place concrete

## Material technology (additional, direction 2):

## System ductility (direction 2):

Ductility unknown

## Plan shape:

Rectangular, solid

## Building position within a block:

One adjacent building

## Vertical structural irregularity - primary:

No irregularity

## Vertical structural irregularity - secondary:

No irregularity

## Roof covering:

Metal sheets

## Roof system type:

Wooden beams/trusses and purlins with light roof

## Floor system type:

Cast-in-place beam-supported RC floor

## Number of storeys below the ground:

Exact number of storeys 0

## Slope of the ground (for buildings on slopes):

Slope of the ground 0

## Occupancy type - detail:

College/university, offices and/or classrooms

## Region (province, state, etc.):

Timisoara

constructed in the 1970's, an RC frame building with masonry infills.