## **GEM Building Taxonomy Report**

Multistorey masonry building Maria BOSTENARU DAN



Taxonomy string:

DX /M99+CLBRS /LWAL /DY /M99+CLBRS /LWAL /YAPP:1920 /HAPP:4+HD:0 /RES+RES2C /BPI /PLFR /IRRE /EWMA /RSH5+RMT1+RWO+RWO2 /FME+FME1 /

Material type (direction 1): Masonry, unknown reinforcement Material properties (direction 1): Mortar type, unknown Lateral load-resisting system (direction 1): Wall Material type (direction 2): Masonry, unknown reinforcement Material properties (direction 2): Mortar type, unknown Lateral load-resisting system (direction 2): Wall Foundations: Unknown foundation system Type of Irregularity: Regular structure Plan structural irregularity - primary: Plan structural irregularity - secondary: Roof shape: Monopitch Roof system material: Wood Roof connections: Roof-wall diaphragm connection unknown Floor system material: Metal Floor connections: Floor-wall diaphragm connection, unknown Exterior walls material: Masonry Date of constrution: Approximate date of construction or retrofit 1920 Number of storeys above the ground: Approximate number of storeys 4 Height of the grade above ground floor: Unknown grade height Occupancy type - general: Residential Country: Romania Observations:

Material technology (direction 1): Fired clay solid bricks Material technology (additional, direction 1):

System ductility (direction 1): Ductility unknown Material technology (direction 2): Fired clay solid bricks Material technology (additional, direction 2):

System ductility (direction 2): Ductility unknown

Plan shape: Rectangular, solid Building position within a block: Interior of block Vertical structural irregularity - primary:

Vertical structural irregularity - secondary:

Roof covering: Tile (clay, concrete) Roof system type: Wooden roof structure supporting a heavy flat or domed roof

Floor system type: Metal beams, trusses or joists supporting light flooring

Number of storeys below the ground: Unknown number of storeys Slope of the ground (for buildings on slopes): Slope of the ground 0 Occupancy type - detail: 5-9 Units Region: Bucharest

This type of building constituted the first middle rise multifamily house in the capital of Romania. The vertical system is of masonry walls, while the horizontal one is out of metal joists supporting also solid clay brick floors.