GEM Building Taxonomy Report

Guard Room_Faizabad Hospital **Amit Kumar**



Taxonomy string:

DX+D99 /W+WLI /LFM+DUC /DY+D99 /W+WLI /LFM+DUC /YEX:2011 /HBET:1,+HF99 /OCO /BPD /PLFRO /IRRE /EWW /RSH2+RMT6+RWO+RWO99+RWCN /FM+FM99+FWC99 /FOSO

Material technology (direction 1): Material type (direction 1): Wood Light wood members Material properties (direction 1): Material techonology (additional, direction 1): Lateral load-resisting system (direction 1): System ductility (direction 1): Ductile Moment frame Material type (direction 2): Material technology (direction 2): Wood Light wood members Material properties (direction 2): Material techonology (additional, direction 2): Lateral load-resisting system (direction 2): System ductility (direction 2): Ductile Moment frame Foundations: Plan shape: Foundation, other Rectangular, with an opening Type of Irregularity: Building position within a block: Regular structure **Detached building** Plan structural irregularity - primary: Vertical structural irregularity - primary:

1-

Plan structural irregularity - secondary:

Roof shape:

Pitched with gable ends Roof system material:

Wood

Roof connections:

Roof-wall diaphragm connection not provided

Floor system material:

Masonry

Floor connections:

Floor-wall diaphragm connection, unknown

Exterior walls material:

Wood

Date of constrution:

Exact date of construction or retrofit 2011

Number of storeys above the ground:

Range of the number of storeys

Height of the grade above ground floor: Height above grade unknown

Occupancy type - general: Other occupancy type

Country: Afghanistan

Summary:

Vertical structural irregularity - secondary:

Roof covering: Metal sheets Roof system type: Wood, unknown

Floor system type: Masonry, unknown

Number of storeys below the ground:

Range of the number of storeys

Slope of the ground (for buildings on slopes):

1-

Unknown slope

Occupancy type - detail:

Region (province, state, etc.):

Badakhshan