GEM Building Taxonomy Report

Smolka_woodframe.pdf Anselm Smolka

Picture not available

Taxonomy string: DX /W+WS / /DY /W+WS / /YEX:1996 /HEX:3+HBEX:1+HFEX:11+HD:5 /RES+RES1 /BPD /PLFR /IRIR+IRPP:REC+IRVP:SET /EWCB /RSH2+RMT1+RWO+RWO4 /FW+FW1 /FOSSL Material type (direction 1): Material technology (direction 1): Wood Solid wood Material properties (direction 1): Material techonology (additional, direction 1): Lateral load-resisting system (direction 1): System ductility (direction 1): Unknown lateral load-resisting system Material technology (direction 2): Material type (direction 2): Solid wood Wood Material properties (direction 2): Material techonology (additional, direction 2): Lateral load-resisting system (direction 2): System ductility (direction 2): Unknown lateral load-resisting system Foundations: Plan shape: Rectangular, solid Shallow foundation, with lateral capacity Type of Irregularity: Building position within a block: Irregular structure Detached building Plan structural irregularity - primary: Vertical structural irregularity - primary: Re-entrant corner No irregularity Vertical structural irregularity - secondary: Plan structural irregularity - secondary: Setback No irregularity Roof shape: Roof covering: Pitched with gable ends Clay or concrete tile Roof system material: Roof system type: Plywood panels or other light-weigth panels for roof Wood Roof connections: Roof-wall diaphragm connection unknown Floor system material: Floor system type: Wood beams/trusses & joists supporting light flooring Wood Floor connections: Floor-wall diaphragm connection, unknown Exterior walls material: Cement-based boards Date of constrution: Exact date of construction or retrofit 1996 Number of storeys above the ground: Number of storeys below the ground: 3 Exact number of storeys Exact number of storeys 1 Slope of the ground (for buildings on slopes): Height of the grade above ground floor: 5 Exact height above grade 11 Slope of the ground Occupancy type - detail: Occupancy type - general: Residential Single dwelling Region (province, state, etc.): Country: Germany Bavaria Summary:

Maybe 10% of detached residential buildings constructed this way